





report date: 2024-03-28

#### General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Black
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2021-07-06
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #10		2020-07-07 10:06
MOT test	number	976499768689
Result		✓ Passed
Next expi	ry date	2021-07-06
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Rear exhaust box rusty	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2019-07-02 10:50
MOT test number	776756521329
Result	✓ Passed

CarCheck.co.uk page 2/10



LT08HYV

report date: 2024-03-28

MOT #8 2018-03-19 10:29

MOT test number 345365054568

**Result** ✓ Passed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #7 2017-03-29 13:27

**MOT test number** 493073848581

MOT #6 2016-03-15 12:48

MOT test number 515597665030

**Result** ✓ Passed

MOT #5 2015-03-20 13:56

**MOT test number** 537139375029

**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Nearside rear tyre starting to crack

MOT #4 2014-02-19 12:44

MOT test number 475940554003

CarCheck.co.uk page 3/10



LT08HYV

report date: 2024-03-28

MOT #3	2013-02-12 13:09
MOT test number	838053143074
Result	<b>✓</b> Passed
MOT #2	2012-02-20 15:18
MOT test number	378741552020
Result	<b>✓</b> Passed
MOT #1	2011-02-14 17:40
MOT test number	737995841070
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

Damage 2

**Type** 

**Date** 

Jaillage 2

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



LT08HYV

report date: 2024-03-28

More info >

## Owner history

o which initially	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
THE STATE OF THE S	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIZ
Flate since	
Current registration	UK SIE
Plate since	

CarCheck.co.uk page 7/10



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

**Contact info** 

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2008-03-01
Last registration	2020-07-07
Complete history	See info



Registration #1	2008-03-01	27 mi
Registration #2	2011-02-14	22.679 mi
Registration #3	2012-02-20	30.437 mi
Registration #4	2013-02-12	36.599 mi
Registration #5	2014-02-19	43.184 mi
Registration #6	2015-03-20	50.285 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		10.377 esc

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1580 kg

## Additional information

-	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

CarCheck.co.uk page 10/10

Number of axles	2

BUD538829

**Engine number**