



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | VOLKSWAGEN     |
| Model               | FOX            |
| Colour              | Grey           |
| Year of manufacture | 2008           |
| Top speed           | 92 mph         |
| 0 - 60 mph          | 17.5 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 55 BHP              |
| Max. torque             | 108 Nm at 3.000 rpm |
| Engine capacity         | 1.198 cc            |
| Cylinders               | 3                   |
| Fuel type               | Petrol              |
| Consumption city        | 36.2 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 46.3 mpg            |
| CO2 emission            | 139 g/km            |
| CO2 label               | E                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-11-05                  |
| Pictures      | 14                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-08 |
| MOT pass rate      | 68 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 6          |
| Total advice items | 22         |
| Total items failed | 10         |

|                  |                  |
|------------------|------------------|
| MOT #19          | 2023-10-04 11:40 |
| MOT test number  | 999031964723     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-10-08       |

|                 |  |
|-----------------|--|
| MOT #18         | 2022-10-06 12:13   |
| MOT test number | 312567401546   |
| Result          | ✓ Passed   |
| Advice          | Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) |

|                         |  |
|-------------------------|--|
| MOT #17                 | 2022-10-06 12:13   |
| MOT test number         | 279867162310   |
| Result                  | ✗ Failed   |
| Pass with rectification | Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))                          |
| Advice                  | Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) |

|                 |   |
|-----------------|---|
| MOT #16         | 2021-10-09 14:28  |
| MOT test number | 703917990371  |
| Result          | ✓ Passed  |
| Minor           | Offside Headlamp lens slightly defective (4.1.1 (b) (i))  |
| Minor           | Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) |

**MOT #15** 2020-11-18 14:55**MOT test number** 258185098934**Result** ✓ Passed

- Advice** Undertrays fitted obscuring some underside components
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #14** 2020-11-18 12:36**MOT test number** 302013822133**Result** ✗ Failed

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Undertrays fitted obscuring some underside components
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #13** 2019-06-14 07:48**MOT test number** 872871358063**Result** ✓ Passed

**MOT #12** 2019-06-14 07:48**MOT test number** 921980129304**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #11** 2018-07-30 09:20**MOT test number** 312342458200**Result** ✓ Passed**MOT #10** 2017-07-26 09:29**MOT test number** 207990457089**Result** ✓ Passed**Advice** Nearside Front worn on outer edge**MOT #9** 2016-07-14 11:07**MOT test number** 685609275064**Result** ✓ Passed**MOT #8** 2016-07-13 09:03**MOT test number** 200833837529**Result** ✗ Failed**Fail** Nearside Front constant velocity joint is excessively worn outter (2.5.C.1b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #7** 2015-07-30 10:58**MOT test number** 508591215231**Result** ✓ Passed**Notice** Nearside rear tyre wearing on outer edge**MOT #6** 2015-07-30 10:58**MOT test number** 599241615231**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Nearside rear tyre wearing on outer edge**MOT #5** 2014-07-30 09:44**MOT test number** 469671114236**Result** ✓ Passed**Notice** Nearside front tyre worn outer edge**Notice** Both front wiper blades deteriorating**MOT #4** 2013-07-25 12:51**MOT test number** 628586003282**Result** ✓ Passed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**MOT #3** 2013-07-25 12:51**MOT test number** 755726003249**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)



|   |                  |
|---|------------------|
| MOT #2  | 2012-07-26 12:33 |
| MOT test number   | 635088002288     |
| Result  | ✓ Passed         |
| <div>NoticeUnder-trays fitted obscuring some underside components</div> |                  |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2011-07-25 11:52 |
| MOT test number | 346546001427     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
8 October 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 June              |
| <b>Days left</b>        | 33                              |
| <b>MOT expiry date</b>  | 8 October 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  GR08EAA |
| Plate since          | 2024-03-29  |
| Current registration |  GR08EAA |
| Plate since          | 2024-03-29  |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2008-08-01               |
| Last registration          | 2023-10-04               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2008-08-01 | 28 mi     |
| Registration #2  | 2011-07-25 | 24.614 mi |
| Registration #3  | 2012-07-26 | 31.573 mi |
| Registration #4  | 2013-07-25 | 39.275 mi |
| Registration #5  | 2014-07-30 | 45.886 mi |
| Registration #6  | 2015-07-30 | 55.875 mi |
| Registration #7  | 2016-07-13 | 66.536 mi |
| Registration #8  | 2016-07-14 | 66.536 mi |
| Registration #9  | 2017-07-26 | 78.705 mi |
| Registration #10 | 2018-07-30 | 90.237 mi |
| Registration #11 | 2019-07-30 | 90.237 mi |
| Registration #12 | 2019-07-30 | 90.237 mi |
| Registration #13 | 2019-07-30 | 90.237 mi |
| Registration #14 | 2019-07-30 | 90.237 mi |
| Registration #15 | 2019-07-30 | 90.237 mi |
| Registration #16 | 2019-07-30 | 90.237 mi |
| Registration #17 | 2019-07-30 | 90.237 mi |
| Registration #18 | 2019-07-30 | 90.237 mi |
| Registration #19 | 2019-07-30 | 90.237 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1660 mm |
| Height              | 1544 mm |
| Length              | 3828 mm |
| Wheel base          | 2465 mm |
| Kerb weight         | 1069 kg |
| Max. allowed weight | 1480 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |

|                 |            |
|-----------------|------------|
| Number of seats | 4          |
| Number of axles | 2          |
| Engine number   | BMD 378141 |