



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 3

Date	2022-10-21
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 2


Date	2022-01-24
Pictures	42
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-22
Pictures	42
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	24
Total items failed	8

MOT #14	2023-10-30 13:58
MOT test number	147307620226
Result	✓ Passed
Next expiry date	2024-11-10
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13**

2023-10-27 09:10

MOT test number

472888976595

Result**✗ Failed**

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))

Fail Offside Front Brakes imbalanced across an axle by more than 50% dragging (1.2.1 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Service brake excessively binding unable to test the wheel bearing (1.2.1 (f))

Fail Offside Rear Tyre has ply or cords exposed 205/50zr17 (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2022-11-11 08:24

MOT test number

766143793406

Result**✓ Passed**

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2022-10-28 08:10

MOT test number

933180263843

Result**✗ Failed**

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre

Fail Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #10** 2021-10-26 15:57**MOT test number** 317702635934**Result** ✓ Passed**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #9** 2021-10-26 08:29**MOT test number** 544804757190**Result** ✗ Failed**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement most rear (5.3.4 (a) (i))**MOT #8** 2020-10-20 13:01**MOT test number** 674709066207**Result** ✓ Passed**MOT #7** 2019-10-22 13:04**MOT test number** 858823030434**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2018-10-19 11:32**MOT test number** 473315685417**Result** ✓ Passed

**MOT #5** 2017-10-17 14:10**MOT test number** 252037332993**Result** ✓ Passed**MOT #4** 2017-10-17 08:02**MOT test number** 617201606148**Result** ✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #3 2016-11-01 10:03**MOT test number** 798649777752**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice N/s/f tyre deep cut on side wall

MOT #2 2015-10-16 10:14**MOT test number** 627651346268**Result** ✓ Passed

Advice Internal headlight adjuster set to 0 to recheck headlight aim

MOT #1 2014-10-15 09:51**MOT test number** 266978484284**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-10-27
Last registration	2023-10-30
Complete history	See info



Registration #1	2011-10-27	7 mi
Registration #2	2014-10-15	30.040 mi
Registration #3	2015-10-16	47.246 mi
Registration #4	2016-11-01	59.176 mi
Registration #5	2017-10-17	64.957 mi
Registration #6	2017-10-17	64.957 mi
Registration #7	2018-10-19	72.005 mi
Registration #8	2019-10-22	75.527 mi
Registration #9	2020-10-20	76.676 mi
Registration #10	2020-10-20	76.676 mi
Registration #11	2020-10-20	76.676 mi
Registration #12	2020-10-20	76.676 mi
Registration #13	2020-10-20	76.676 mi
Registration #14	2020-10-20	76.676 mi
Registration #15	2020-10-20	76.676 mi
Registration #16	2020-10-20	76.676 mi
Registration #17	2020-10-20	76.676 mi
Registration #18	2020-10-20	76.676 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212