



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Yellow
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-18
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	38
Total items failed	21

MOT #15	2024-03-19 12:35
MOT test number	498158208931
Result	✓ Passed
Next expiry date	2025-03-18

MOT #14	2024-03-15 13:20
MOT test number	358283151361
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #13	2023-03-16 09:35
MOT test number	824009573503
Result	✓ Passed

MOT #12	2022-05-23 16:36
MOT test number	340188008664
Result	✓ Passed

**MOT #11**

2022-05-18 14:42

MOT test number

122102612814

Result**✗ Failed**

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Rear Exhaust heatshield insecure

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Strut bearing sticking

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 205/45/17 (5.2.3 (e))

Advice Nearside Sill trim insecure

Fail Nearside Brake cable damaged (1.1.15 (a))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #10

2021-06-07 11:20

MOT test number

938839624929

Result**✓ Passed**

Advice Oil leak at oil filter housing

Advice Both exhaust rear mounts excessive corroded and fractured

Advice Oil leak at drivers drive shaft gear box seal

**MOT #9** 2021-06-07 11:20**MOT test number** 350850465510**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Oil leak at oil filter housing**Advice** Both exhaust rear mounts excessive corroded and fractured**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Oil leak at drivers drive shaft gear box seal**MOT #8** 2020-11-26 16:20**MOT test number** 108616624918**Result** ✓ Passed**MOT #7** 2019-12-03 16:50**MOT test number** 776276324989**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing starting to show surface cracks + offside same (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #6**

2019-11-30 12:46

MOT test number

379215486128

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing starting to show surface cracks + offside same (5.2.3 (d) (ii))**Fail** Offside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #5**

2018-11-23 11:41

MOT test number

750239456928

Result**✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #4** 2018-11-23 09:39**MOT test number** 252871164183**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Exhaust system insecure (6.1.2 (a))**MOT #3** 2017-11-24 09:37**MOT test number** 324851304057**Result** ✓ Passed**MOT #2** 2016-11-25 15:58**MOT test number** 630929131411**Result** ✓ Passed**MOT #1** 2016-02-03 11:44**MOT test number** 963855079062**Result** ✓ Passed**Advice** Nearside Rear Outer brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front tyre sidewall cut but not showing cord**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Outer brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
18 March 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 KS62KCZ
Plate since	2019-09-29
Current registration	 KS62KCZ
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-02-25
Last registration	2024-03-19
Complete history	See info



Registration #1	2013-02-25	23 mi
Registration #2	2016-02-03	15.203 mi
Registration #3	2016-11-25	18.625 mi
Registration #4	2017-11-24	26.176 mi
Registration #5	2018-11-23	33.931 mi
Registration #6	2018-11-23	33.931 mi
Registration #7	2019-11-30	43.269 mi
Registration #8	2019-12-03	43.271 mi
Registration #9	2020-11-26	51.591 mi
Registration #10	2020-11-26	51.591 mi
Registration #11	2020-11-26	51.591 mi
Registration #12	2020-11-26	51.591 mi
Registration #13	2020-11-26	51.591 mi
Registration #14	2020-11-26	51.591 mi
Registration #15	2020-11-26	51.591 mi
Registration #16	2020-11-26	51.591 mi
Registration #17	2020-11-26	51.591 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3067047