





General information

Make	JAGUAR
Model	S-TYPE V6
Colour	Blue
Year of manufacture	2002
Top speed	141 mph
0 - 60 mph	6.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	300 Nm at 4.500 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.0 mpg
Consumption extra urban	31.0 mpg
Consumption combined	23.9 mpg
CO2 emission	285 g/km
CO2 label	М







Internet history

Entry 2 Date

Pictures

2021-07-31

25

Listing price

View report



source: cargurus.co.uk

Entry 1	
Date	2021-07-30
Pictures	25
Listing price	View report



source: autotrader.co.uk









MOT history

MOT expiry date	2024-08-25
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	37
Total items failed	0

MOT #20		2023-08-24 11:51
MOT test nu	umber	362128446073
Result		Passed
Next expiry	date	2024-08-25
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #19	2022-08-26 12:01
MOT test number	697617583509
Result	✓ Passed
Advice All 4 tyres are cracked and perished	

MOT #18	2021-08-25 09:43
MOT test number	841984758899
Result	✓ Passed



MOT #17		2021-08-19 15:43
MOT test	number	997556364204
Result		🗙 Failed
MAJOR	Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Rear Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR	Brake lever has insufficient reserve travel (1.1.2 (a))	
MAJOR	Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Nearside Rear Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

МОТ #16	2019-12-23 16:10
MOT test number	914636021309
Result	✓ Passed
Minor Nearside Rear Track rod end ball joint dust cover damaged or deteriorated, ingress of dirt (2.1.3 (g) (i))	but preventing the
Advice Rear Brake pipe corroded, covered in grease or other material both sides (1	l.1.11 (c))
Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorat	ed (5.3.4 (b) (i))
Advice Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))
Minor Offside Rear Track rod end ball joint dust cover damaged or deteriorated, buildingress of dirt (2.1.3 (g) (i))	ut preventing the
Advice Front Power steering pipe/hose has slight seepage (2.1.5 (a))	






MOT #15	2019-12-19 11:04
MOT test number	641268723939
Result	🗙 Failed
Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriora	ated (5.3.4 (b) (i))
Advice Front Brake pipe corroded, covered in grease or other material both sides	(1.1.11 (c))
Minor Offside Rear Track rod end ball joint dust cover damaged or deteriorated, be ingress of dirt (2.1.3 (g) (i))	out preventing the
Advice Front Power steering pipe/hose has slight seepage (2.1.5 (a))	
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	
Minor Nearside Rear Track rod end ball joint dust cover damaged or deteriorated, ingress of dirt (2.1.3 (g) (i))	but preventing the
Advice Rear Brake pipe corroded, covered in grease or other material both sides	(1.1.11 (c))
DANGEROUS Nearside Front Brake hose connection leaking on a hydraulic brakin	ıg system (1.1.12 (c) (ii))

MOT #14	2018-12-04 11:04
MOT test	number 878887343484
Result	✓ Passed
Advice	Offside Front Power steering pipe/hose has slight seepage on steering rack (2.1.5 (a))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13	2017-12-07 10:58	8
MOT test	number 211401752269	<u>)</u>
Result	✓ Passed	b
Advice (2.4.G.2)	Nearside Rear Radius arm ball joint dust cover damaged, but preventing the ingress of dirt	
Advice	Power steering pipe(s) or hose(s) has slight seepage pipe to rack (2.3.3b)	
Advice of dirt (2.4	Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress .G.2)	
Advice	Offside Rear Radius arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)	



MOT #12	2016-12-12 11:00
MOT test number	714242072386
Result	✓ Passed
Advice Offside Front Lower Suspension arm ball joint dust cover of dirt (2.4.G.2)	r deteriorated, but preventing the ingress
Advice Nearside Front Lower Suspension arm ball joint dust covingress of dirt (2.4.G.2)	er deteriorated, but preventing the
MOT #11	2015-12-10 13:08
MOT test number	599805933522
Result	✓ Passed
Advice Coolant leak	
MOT #10	2014-12-09 12:26
MOT test number	277693344328
Result	✓ Passed
MOT #9	2013-12-11 10:58
MOT test number	426715643415
Result	✓ Passed
Advice Power steering pipe(s) or hose(s) slightly corroded (2.3.2	2)
MOT #8	2012-12-14 10:53
MOT test number	499539442407
Result	✓ Passed
MOT #7	2011-12-14 11:47
MOT test number	545208441319
Result	✓ Passed







МОТ #6	2010-12-14 11:06
MOT test number	402568140301
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #5	2009-12-08 11:57
MOT test number	444062449346
Result	✓ Passed
Notice O/s/f tyre tread wearing	
MOT #4	2008-12-10 12:09
MOT test number	761585848338
Result	✓ Passed
MOT #3	2007-12-11 14:25
MOT test number	791215647369
Result	✓ Passed
MOT #2	2007-01-02 10:43
MOT test number	110902907432
Result	✓ Passed
MOT #1	2005-12-13 09:33
MOT test number	414027645324
Result	Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 September 2024 Tax status	Expires: 25 August 2024 Valid until 1 September
Days left	124
MOT expiry date	25 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-01-06
Last registration	2023-08-24
Complete history	See info



Registration #2 2005-12-13 28.397 m Registration #3 2007-01-02 32.888 m Registration #4 2007-12-11 34.963 m Registration #5 2008-12-10 36.428 m Registration #6 2009-12-08 37.093 m Registration #7 2010-12-14 37.973 m Registration #8 2011-12-14 38.819 m Registration #9 2012-12-14 40.110 m Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m			
Registration #3 2007-01-02 32.888 m Registration #4 2007-12-11 34.963 m Registration #5 2008-12-10 36.428 m Registration #6 2009-12-08 37.093 m Registration #6 2010-12-14 37.973 m Registration #7 2010-12-14 38.819 m Registration #8 2011-12-14 38.819 m Registration #10 2013-12-11 40.810 m Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 T T Registration #14 T T T Registration #15 T T T Registration #16 T T T T Registration #18 T T T T T Registration #19 T T T T T T Registration #20 T T T T T T T T T T T	Registration #1	2002-01-06	26 mi
Registration #4 2007-12-11 34.963 m Registration #5 2008-12-10 36.428 m Registration #6 2009-12-08 37.093 m Registration #6 2010-12-14 37.973 m Registration #7 2010-12-14 38.819 m Registration #8 2011-12-14 38.819 m Registration #9 2012-12-14 40.110 m Registration #10 2013-12-11 40.861 m Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 E E Registration #14 E E Registration #15 E E Registration #16 E E Registration #17 E E Registration #19 E E Registration #20 E E Registration #21 E E Registration #22 E E	Registration #2	2005-12-13	28.397 mi
Registration #5 2008-12-10 36.428 m Registration #6 2009-12-08 37.093 m Registration #7 2010-12-14 37.973 m Registration #7 2010-12-14 38.819 m Registration #8 2011-12-14 38.819 m Registration #9 2012-12-14 40.110 m Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 Image: Station #13 Image: Station #14 Registration #16 Image: Station #16 Image: Station #16 Registration #17 Image: Station #17 Image: Station #17 Registration #18 Image: Station #19 Image: Station #10 Registration #19 Image: Station #20 Image: Station #20 Registration #21 Image: Station #22 Image: Station #22	Registration #3	2007-01-02	32.888 mi
Registration #6 2009-12-08 37.093 m Registration #7 2010-12-14 37.973 m Registration #8 2011-12-14 38.819 m Registration #8 2012-12-14 40.110 m Registration #9 2012-12-14 40.861 m Registration #10 2013-12-11 40.861 m Registration #10 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 Image: Station #13 Image: Station #13 Registration #14 Image: Station #14 Image: Station #15 Registration #16 Image: Station #16 Image: Station #17 Registration #17 Image: Station #18 Image: Station #19 Registration #20 Image: Station #20 Image: Station #21 Registration #21 Image: Station #21 Image: Station #20	Registration #4	2007-12-11	34.963 mi
Registration #7 2010-12-14 37.973 m Registration #8 2011-12-14 38.819 m Registration #9 2012-12-14 40.110 m Registration #10 2013-12-11 40.861 m Registration #10 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 T T Registration #14 T T Registration #15 T T Registration #16 T T Registration #17 T T Registration #18 T T Registration #19 T T Registration #20 T T Registration #21 T T	Registration #5	2008-12-10	36.428 mi
Registration #8 2011-12-14 38.819 m Registration #9 2012-12-14 40.110 m Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 2015-12-10 42.712 m Registration #14 40.000 40.000 Registration #14 40.000 40.000 Registration #15 40.000 40.000 Registration #16 40.000 40.000 Registration #17 40.000 40.000 Registration #19 40.000 40.000 Registration #20 40.000 40.000 Registration #21 40.000 40.000 Registration #22 40.000 40.000	Registration #6	2009-12-08	37.093 mi
Registration #9 2012-12-14 40.110 m Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 1 1 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1 Registration #17 1 1 Registration #18 1 1 Registration #19 1 1 Registration #20 1 1 Registration #21 1 1	Registration #7	2010-12-14	37.973 mi
Registration #10 2013-12-11 40.861 m Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13 Image: Constraint of the second sec	Registration #8	2011-12-14	38.819 mi
Registration #11 2014-12-09 41.730 m Registration #12 2015-12-10 42.712 m Registration #13	Registration #9	2012-12-14	40.110 mi
Registration #122015-12-1042.712 mRegistration #13	Registration #10	2013-12-11	40.861 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #11	2014-12-09	41.730 mi
Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22	Registration #12	2015-12-10	42.712 mi
Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22	Registration #13		11.117 esi
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #14		11.112 esi
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #15		11.222 esi
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #16		11.112 esi
Registration #19 Registration #20 Registration #21 Registration #22	Registration #17		11.222 esi
Registration #20 Registration #21 Registration #22	Registration #18		11.112 esi
Registration #21 Registration #22	Registration #19		11.222 esi
Registration #22	Registration #20		11.317 est
	Registration #21		11.117 esi
Registration #23	Registration #22		11.117 esi
	Registration #23		11.227 esi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1819 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1630 kg
Additional information	
Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	183294363FB