





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 PURETECH FLAIR
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



AO15CPN report date: 2024-03-28

MOT history

MOT expiry date	2025-05-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #9		2024-04-19 16:27
MOT test	number	229889688404
Result		✓ Passed
Next expi	ry date	2025-05-17
Advice Offside Rear Tyre slightly damaged Damage to outer side wall. (5.2.3 (d) (ii))		
Advice	Front Brake disc worn, but not excessively Both sides also lipped on edge	s. (1.1.14 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2024-04-19 08:31

MOT test number 964883077699

Result X Failed

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Very badly perishing/cracking on outer shoulder and close to limit, no cords visible. *ADVISE REPLACEMENT* (5.2.3 (d) (ii))

Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides also have corrosion on braking faces. (1.1.14 (a) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Tyre slightly damaged/cracking or perishing Very badly perishing/cracking on outer shoulder and worn on edges, no cords visible. *ADVISE REPLACEMENT* (5.2.3 (d) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Brake pad(s) wearing thin Inner pad both sides very close to limit. *Advise Replacement* (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively Both sides also lipped on edges. (1.1.14 (a) (i))

Advice Nearside Front Tyre slightly damaged Damage to outer side wall. (5.2.3 (d) (ii))

MOT #7 2023-04-18 09:34

MOT test number 260491445984

Result

Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2022-04-26 10:28

MOT test number 426312030423

Result \rightarrow Passed

MOT #5 2021-05-18 10:30

MOT test number 267883801692

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

✓ Passed

MOT #4 2021-04-21 10:38

MOT test number 550729083995

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #3 2020-03-20 16:56

MOT test number 710677660608

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-03-20 12:07

MOT test number 684344750199

Result
✓ Passed

Advice Nearside Rear Nail in tyre

Advice Oil leak

Result

MOT #1 2018-03-16 11:07

MOT test number 914450809701

Result

Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	17 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

^ -		histor	-
- () ()	vnor	nistar	٦.
\smile	VIICI	пизсоп	·v

,	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-26
Last registration	2024-04-19
Complete history	See info



Registration #1	2015-03-26	17 mi
Registration #2	2018-03-16	18.232 mi
Registration #3	2019-03-20	27.057 mi
Registration #4	2020-03-20	34.767 mi
Registration #5		11.777 es
Registration #6	2021-04-21	36.804 mi
Registration #7		9.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 66
Registration #11		0.00 es

More info >

CarCheck.co.uk page 11/12



AO15CPN report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150067940

CarCheck.co.uk page 12/12