





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|----------------|
| Model | MINI (R60) ONE |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 107 mph |
| 0 - 60 mph | 11.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 98 BHP |
|-------------------------|---------------------|
| Max. torque | 153 Nm at 3.000 rpm |
| Engine capacity | 1.600 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-04-18

Pictures 39

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-29

| Μ | OT | his | tory |
|---|----|-----|------|
| | | | |

| MOT expiry date | 2025-04-20 |
|--------------------|------------|
| MOT pass rate | 79 % |
| MOT passed | 11 |
| Failed MOT tests | 3 |
| Total advice items | 28 |
| Total items failed | 5 |

| MOT #14 | 2024-03-26 17:05 |
|------------------|------------------|
| MOT test number | 900272216942 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-20 |

| MOT #13 | 2024-03-26 12:25 |
|--|------------------|
| MOT test number | 216231100040 |
| Result | ★ Failed |
| Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) | |
| Fail Offside Parking brake inoperative on one side (1.4.1 (a)) | |

| MOT #12 | | 2023-04-06 14:09 |
|----------------------|--|-----------------------|
| MOT test | number | 369543402167 |
| Result | | ✓ Passed |
| Advice | Brake disc worn, but not excessively Front & Rears - Slightly Lipped (1.1 | 1.14 (a) (i)) |
| Advice Centre (5. | Front Tyre slightly damaged/cracking or perishing Both Starting to Sligh 2.3 (d) (ii)) | itly Crack & 3-4mm in |

| MOT #11 | 2022-04-21 14:21 |
|-----------------|------------------|
| MOT test number | 421940763538 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2022-02-28 12:51 998809101212 **MOT** test number ✓ Passed Result **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Vehicle fitted with under bonnet covers preventing full inspection Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Vehicle fitted with under body covers preventing full inspection Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice **Advice** Exhaust flexi loose and broken but not leaking at time of test

| MOT #9 | | 2021-02-03 15:43 |
|----------|--|------------------|
| MOT test | number | 170110299772 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Under trays and engine covers fitted | |

| MOT #8 | 2021-02-03 13:57 |
|---|------------------|
| MOT test number | 680676019933 |
| Result | X Failed |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Fail Nearside Front Lower Position lamp not working (4.2.1 (a) (ii)) | |
| Advice Under trays and engine covers fitted | |

CarCheck.co.uk page 4/13



report date: 2024-03-29

| MOT #7 | | 2020-01-30 17:05 |
|----------|--|------------------|
| MOT test | number | 420000660956 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) | |
| Advice | Engine covers fitted preventing full under bonnet inspection | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Under trays fitted preventing full under body inspection | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #6 | | 2019-02-06 10:52 |
|----------|--|------------------|
| MOT test | number | 743675745688 |
| Result | | ✓ Passed |
| Advice | Both rear tyre are perished | |
| Advice | Engine covers fitted preventing full under bonnet inspection | |
| Advice | Brake reaction bushes are soft | |
| Advice | Undertrays fitted preventing full underside inspection | |

| MOT #5 | 2018-01-12 14:51 |
|--|------------------|
| MOT test number | 628170645531 |
| Result | ✓ Passed |
| Advice O/S/R tyre sidewalls and tread perished Advice N/S/R tyre sidewalls and tread perished | |

CarCheck.co.uk page 5/13



report date: 2024-03-29

| MOT #4 | 2017-12-28 11:48 |
|---|------------------|
| MOT test number | 881315493507 |
| Result | × Failed |
| Advice O/S/R tyre sidewalls and tread perished | |
| Fail Nearside Front position lamp(s) not working (1.1.A.3b) | |
| Advice N/S/R tyre sidewalls and tread perished | |
| Fail Parking brake lever has no reserve travel (3.1.6b) | |

| MOT #3 | 2017-01-06 13:48 |
|---|------------------|
| MOT test number | 579864313282 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2016-01-11 11:00 |
| MOT test number | 430429403306 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2015-01-12 13:51 |
| MOT test number | 148422115406 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 125 |
| MOT expiry date | 20 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

| e union motory | |
|--|-------------|
| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u> | |
| ******** | |
| | |
| *************************************** | |
| | |
| | |
| ************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | OK SIE |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courte at Info | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2011-09-12 |
| Last registration | 2024-03-26 |
| Complete history | See info |



| Registration #1 | 2011-09-12 | 9 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-01-12 | 24.705 mi |
| Registration #3 | 2016-01-11 | 28.578 mi |
| Registration #4 | 2017-01-06 | 31.548 mi |
| Registration #5 | 2017-12-28 | 34.349 mi |
| Registration #6 | 2018-01-12 | 34.349 mi |
| Registration #7 | 2019-02-06 | 37.064 mi |
| Registration #8 | 2020-01-30 | 39.591 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| | | |

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 0501 | |
| 0566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1789 mm |
|---------------------|---------|
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1265 kg |
| Max. allowed weight | 1735 kg |

Additional information

| Fuel tank capacity | 47 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13 |

Number of axles2Engine numberA767J014