



MA04HOJ

report date: 2024-03-28

General information

Make	SUZUKI
Model	IGNIS GL VVT-S
Colour	Silver
Year of manufacture	2004
Top speed	103 mph
0 - 60 mph	11.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	98 BHP
Max. torque	133 Nm at 4.100 rpm
Engine capacity	1.490 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H





## MOT history

MOT expiry date	2021-03-09
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	27
Total items failed	14

MOT #22	2020-03-03 09:27
MOT test number	196080270375
Result	✓ Passed
Next expiry date	2021-03-09

MOT #21	2019-03-04 14:51
MOT test number	463316051957
Result	✓ Passed

MOT #20	2019-03-04 11:17
MOT test number	830666463114
Result	✗ Failed

**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))

MOT #19	2018-03-06 12:02
MOT test number	538698808133
Result	✓ Passed

**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)



MOT #18 2018-02-26 11:53

MOT test number 193712061224

Result ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 165 70 14 (4.1.E.1)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Fail** Exhaust system not adequately supported front AND rear hanger welds off (7.1.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Brakes imbalanced across an axle 36% (3.7.B.5b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #17 2017-03-08 13:07

MOT test number 211731094688

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both on inner faces (3.5.1i)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #16**

2017-03-02 09:26

**MOT test number**

191029124784

**Result**

✗ Failed

**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Nearside Rear Suspension arm corroded and seriously weakened (2.4.G.1)**Fail** Offside Rear Brake pipe excessively corroded front to rear at flexi end (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Brake pipe excessively corroded front to rear at flexi end (3.6.B.2c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both on inner faces (3.5.1i)**MOT #15**

2016-03-07 17:15

**MOT test number**

507152199935

**Result**

✓ Passed

**Advice** Offside Rear Brake pipe slightly corroded at flexi hose (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded at flexi hose (3.6.B.2c)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #14**

2015-02-26 10:14

**MOT test number**

979227155052

**Result**

✓ Passed

**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #13** 2015-02-24 17:15**MOT test number** 956145955001**Result** ✗ Failed

**Fail** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)

**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**Fail** Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)

**MOT #12** 2014-03-06 15:41**MOT test number** 906015664014**Result** ✓ Passed

**Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)

**MOT #11** 2014-03-06 11:36**MOT test number** 569685464090**Result** ✗ Failed

**Fail** Rear registration plate insecure (6.3.1b)

**Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)

**Fail** Offside Rear wheel bearing rough when rotated (2.6.1)

**MOT #10** 2013-03-06 16:52**MOT test number** 468385263096**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2012-03-03 10:49**MOT test number** 336623162017**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2011-02-28 10:14**MOT test number** 655579451043**Result** ✓ Passed**MOT #7** 2010-03-03 11:11**MOT test number** 763042560007**Result** ✓ Passed**MOT #6** 2010-03-02 11:10**MOT test number** 153221760485**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Front Exhaust mounting missing (7.1.1b)**MOT #5** 2009-03-05 17:14**MOT test number** 670574969029**Result** ✓ Passed**MOT #4** 2009-03-03 12:21**MOT test number** 154222069429**Result** ✗ Failed**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)



MOT #3	2008-03-07 12:10
MOT test number	120687668444
Result	✓ Passed

MOT #2	2008-03-06 13:17
MOT test number	311546868039
Result	✗ Failed
Fail	Offside Front wheel bearing rough when rotated (2.5.A.2)

MOT #1	2007-03-06 13:23
MOT test number	163765167073
Result	✓ Passed
Notice	Wear to n/s/f tyre



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-09
Last registration	2020-03-03
Complete history	<a href="#">See info</a>



Registration #1	2004-03-09	21 mi
Registration #2	2007-03-06	17.257 mi
Registration #3	2008-03-06	22.112 mi
Registration #4	2008-03-07	22.116 mi
Registration #5	2009-03-03	25.464 mi
Registration #6	2009-03-05	25.497 mi
Registration #7	2010-03-02	27.854 mi
Registration #8	2010-03-03	27.856 mi
Registration #9	2011-02-28	30.777 mi
Registration #10	2012-03-03	35.059 mi
Registration #11	2013-03-06	39.193 mi
Registration #12	2014-03-06	43.110 mi
Registration #13	2015-03-06	47.027 mi
Registration #14	2016-03-06	50.944 mi
Registration #15	2017-03-06	54.861 mi
Registration #16	2018-03-06	58.778 mi
Registration #17	2019-03-06	62.695 mi
Registration #18	2020-03-03	66.612 mi
Registration #19	2021-03-03	70.529 mi
Registration #20	2022-03-03	74.446 mi
Registration #21	2023-03-03	78.363 mi
Registration #22	2024-03-03	82.280 mi
Registration #23	2025-03-03	86.197 mi

More info >



Dimensions & weight

Width	1605 mm
Height	1605 mm
Length	3770 mm
Wheel base	2360 mm
Kerb weight	1010 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	M15A-1037680