



General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | POLO GTI |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 147 mph |
| 0 - 100 km/h | 6.7 seconds |
| 0 - 60 mph | 6.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 141 kW / 192 HP / 189 BHP |
| Max. torque | 250 Nm at 1.300 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-08 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-28 |
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 0 |

MOT #7 2023-11-25 09:45

MOT test number 755185658680

Result ✓ Passed

Next expiry date 2024-11-28

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6 2022-11-10 11:28

MOT test number 559091655595

Result ✓ Passed

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #5 2021-11-29 17:44

MOT test number 215308912728

Result ✓ Passed



| | |
|--|------------------|
| MOT #4 | 2021-11-29 09:56 |
| MOT test number | 241045047353 |
| Result | ✗ Failed |
| MAJOR Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i)) | |

| | |
|-----------------|------------------|
| MOT #3 | 2021-04-14 15:34 |
| MOT test number | 650174728433 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #2 | 2020-07-27 09:56 |
| MOT test number | 404718732624 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2019-07-20 10:55 |
| MOT test number | 259328677052 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 28 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YG16NMT |
| Plate since | 2019-09-29 |
| Current registration | YG16NMT |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2016-07-29 |
| Last registration | 2023-11-25 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2016-07-29 | 22 mi |
| Registration #2 | 2019-07-20 | 20.818 mi |
| Registration #3 | 2020-07-27 | 29.118 mi |
| Registration #4 | 2021-04-14 | 30.613 mi |
| Registration #5 | 2023-11-25 | 31.277 mi |
| Registration #6 | 2023-11-25 | 31.277 mi |
| Registration #7 | 2023-11-25 | 31.277 mi |
| Registration #8 | 2023-11-25 | 31.277 mi |
| Registration #9 | 2023-11-25 | 31.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 86% |
| Pedestrian | 41% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1901 mm |
| Height | 1462 mm |
| Length | 3972 mm |
| Wheel base | 2470 mm |
| Kerb weight | 1172 kg |
| Max. allowed weight | 1710 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |

| | |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DAJA014876 |