





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|----------------|
| Model | NOTE ACENTA |
| Colour | Blue |
| Year of manufacture | 2015 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 80 BHP |
|-------------------------|---------------------|
| Max. torque | 110 Nm at 4.000 rpm |
| Engine capacity | 1.198 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 109 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-07

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-06-11 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 21 |
| Total items failed | 1 |

| MOT #7 | 2023-06-05 10:02 |
|---|------------------|
| MOT test number | 853762340398 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-11 |
| Advice Items removed from driver's view prior to test | |

| MOT #6 | | 2022-06-09 13:57 |
|----------|--|------------------|
| MOT test | number | 274825131890 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/12



MOT #5

Advice

ND15HMH

report date: 2024-03-29

2021-06-08 16:13

MOT test number

Result

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2021-06-07 10:13

MOT test number 407873243794

Result × Failed **Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Nearside Front Suspension arm pin or bush likely to become detached Outer bush split (5.3.4 (a) (ii)) Fail Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

| MOT #3 | 2020-05-18 11:06 |
|--|------------------|
| MOT test number | 404048611992 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2019-06-03 11:39 |
| MOT test number | 268909353144 |
| Result | ✓ Passed |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |

| MOT #1 | 2018-06-04 11:35 |
|-----------------|------------------|
| MOT test number | 816904515614 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



ND15HMH report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 125 |
| MOT expiry date | 11 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

| o which initiating | |
|--|-------------|
| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
| | |
| | |
| | |
| | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-06-12 |
| Last registration | 2023-06-05 |
| Complete history | See info |



| Registration #1 | 2015-06-12 | 14 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-06-04 | 14.741 mi |
| Registration #3 | 2019-06-03 | 17.804 mi |
| Registration #4 | 2020-05-18 | 20.735 mi |
| Registration #5 | 2021-06-07 | 24.370 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 9.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 11/12



ND15HMH report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 86% |
| Children | 82% |
| Pedestrian | 58% |
| Safety systems | 70% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1695 mm |
|---------------------|---------|
| Height | 1530 mm |
| Length | 4100 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1040 kg |
| Max. allowed weight | 1510 kg |

Additional information

| Fuel tank capacity | 41 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles 2

Engine number 094515R