



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA SPORT TDI (115BHP)
Colour	Blue
Year of manufacture	2001
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	284 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 2

Date	2022-02-09
Pictures	37
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-08
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-02
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	42
Total items failed	14

MOT #262023-07-03 10:27

MOT test number291904841976

Result✓ Passed

Next expiry date2024-07-02

- AdviceOil leak, but not excessive (8.4.1 (a) (i))
- AdviceDrive belt worn, but not excessively (6.1.7 (c) (i))
- AdviceCentral Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceNearside Front Play in steering rack inner joint(s)
- AdviceNearside Rear Service brake binding but not excessively (1.2.1 (f))
- AdviceFront Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

**MOT #25**

2023-06-21 15:11

MOT test number

835377205620

Result**✗ Failed**

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Central Rear Brake pipe excessively corroded both sides marked with yellow (1.1.11 (c))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))
- MAJOR** Offside Front Outer Drive shaft flexible coupling excessively deteriorated (6.1.7 (d) (i))

MOT #24

2022-06-15 16:49

MOT test number

616205230476

Result**✓ Passed**

- Advice** Nearside Front steering rack inner joint slight play
- Advice** Rear Brake pipe corroded, covered in grease or other material o/s and n/s (1.1.11 (c))
- Advice** Offside Front Outer c/v boot slight off grease
- Advice** Front Brake hose has slight corrosion to ferrule o/s and n/s (1.1.12 (f) (i))



MOT #23	2022-06-14 11:52
MOT test number	285431870400
Result	✗ Failed
MAJOR	Offside Rear Brake cable damaged split open on outer casing (1.1.15 (a))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Front Outer c/v boot slight off grease
Advice	Rear Brake pipe corroded, covered in grease or other material o/s and n/s (1.1.11 (c))
MAJOR	Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
Advice	Nearside Front steering rack inner joint slight play
Advice	Front Brake hose has slight corrosion to ferrule o/s and n/s (1.1.12 (f) (i))

MOT #22	2021-06-18 12:11
MOT test number	812366391766
Result	✓ Passed

MOT #21	2020-06-06 08:24
MOT test number	608377368097
Result	✓ Passed

MOT #20	2020-06-06 08:24
MOT test number	347964157367
Result	✗ Failed
Pass with rectification	Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #19	2019-06-20 14:12
MOT test number	357188986795
Result	✓ Passed

**MOT #18** 2019-06-20 14:12**MOT test number** 231495132310**Result** ✗ Failed

Pass with rectification Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #17 2018-06-19 15:54**MOT test number** 735695326839**Result** ✓ Passed

Advice Offside Rear Brake cable damaged but not to excess outer case corroded and splitting (1.1.15 (a))

MOT #16 2017-06-22 14:39**MOT test number** 500157877963**Result** ✓ Passed**MOT #15** 2016-06-06 10:33**MOT test number** 469831967090**Result** ✓ Passed

Advice Exhaust heat shield loose

Advice Exhaust rear bracket corroded/detached

MOT #14 2016-06-06 10:33**MOT test number** 212498012661**Result** ✗ Failed

Pass with rectification Offside Headlamp aim too high (1.8)

Advice Exhaust rear bracket corroded/detached

Pass with rectification Nearside Front Inner Front constant velocity joint is insecure (2.5.C.1b)

Advice Exhaust heat shield loose

**MOT #13** 2015-06-05 10:02**MOT test number** 667026255100**Result** ✓ Passed**MOT #12** 2014-05-30 11:49**MOT test number** 137710854149**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #11** 2013-06-04 13:59**MOT test number** 338535153154**Result** ✓ Passed**MOT #10** 2013-06-03 09:30**MOT test number** 787104653166**Result** ✗ Failed**Notice** Nearside inner cv gaiter outer clip is missing**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Notice** Nearside outer cv gaiter is pin holed**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front coil spring incomplete (2.4.C.1a)

**MOT #9** 2012-06-11 17:09**MOT test number** 275553662487**Result** ✓ Passed

- Notice** Nearside outer cv gaiter is slightly pin holed
- Notice** Both front suspension wishbones, rear bushes are starting to delaminate
- Notice** Front to rear brake pipes, rear section is slightly corroded

MOT #8 2012-06-11 17:09**MOT test number** 945783062132**Result** ✗ Failed

- Notice** Nearside outer cv gaiter is slightly pin holed
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Notice** Both front suspension wishbones, rear bushes are starting to delaminate
- Notice** Front to rear brake pipes, rear section is slightly corroded
- Pass with rectification** Offside Headlamp aim too low and too far to the right. (1.8)

MOT #7 2011-03-29 09:56**MOT test number** 149178481052**Result** ✓ Passed**MOT #6** 2010-04-01 17:56**MOT test number** 853851790015**Result** ✓ Passed

**MOT #5** 2010-04-01 12:09**MOT test number** 791701890000**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear brake disc excessively pitted (3.5.1h)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**Fail** Offside Rear brake disc excessively pitted (3.5.1h)**MOT #4** 2009-02-26 09:22**MOT test number** 521737559035**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2008-02-14 16:36**MOT test number** 120535448071**Result** ✓ Passed**MOT #2** 2007-02-05 12:09**MOT test number** 362066437067**Result** ✓ Passed**Advice** Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**MOT #1** 2006-02-15 14:04**MOT test number** 440056946015**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
2 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 Y76BGB
Plate since	2024-03-29
Current registration	 Y76BGB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2001-06-01
Last registration	2023-07-03
Complete history	See info



Registration #1	2001-06-01	13 mi
Registration #2	2006-02-15	59.089 mi
Registration #3	2007-02-05	66.780 mi
Registration #4	2008-02-14	70.807 mi
Registration #5	2009-02-26	74.456 mi
Registration #6	2010-04-01	79.515 mi
Registration #7	2010-04-01	79.515 mi
Registration #8	2011-03-29	82.227 mi
Registration #9	2012-06-11	82.235 mi
Registration #10	2013-06-03	83.229 mi
Registration #11	2013-06-04	83.229 mi
Registration #12	2014-05-30	83.975 mi
Registration #13	2015-06-05	85.371 mi
Registration #14	2016-06-06	88.012 mi
Registration #15	2016-06-06	88.012 mi
Registration #16	2016-06-06	88.012 mi
Registration #17	2016-06-06	88.012 mi
Registration #18	2016-06-06	88.012 mi
Registration #19	2016-06-06	88.012 mi
Registration #20	2016-06-06	88.012 mi
Registration #21	2016-06-06	88.012 mi
Registration #22	2016-06-06	88.012 mi
Registration #23	2016-06-06	88.012 mi
Registration #24	2016-06-06	88.012 mi
Registration #25	2016-06-06	88.012 mi
Registration #26	2016-06-06	88.012 mi

Registration #27	2023-25-27	25,277-462
Registration #28	2023-25-28	25,277-462

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2018 mm
Height	1446 mm
Length	4376 mm
Wheel base	2519 mm

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	AJM364781