





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	ML ML250 BLUETEC SPECIAL EDITION
Colour	White
Year of manufacture	2012
Top speed	130 mph
0 - 100 km/h	9.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.8 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-12-01

Pictures 82

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-21
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #14		2023-12-22 08:26
MOT test no	umber	800781492784
Result		✓ Passed
Next expiry	date date	2024-12-21
Minor F	ront Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 255 50 R19 (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #13	2023-12-18 14:48
MOT test number	426363984997
Result	× Failed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge 255 50 R19 (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



X Failed

MOT #12 2022-12-02 16:12

MOT test number 439441004115

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2022-12-02 11:08

MOT test number 942960656649

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2021-12-03 11:50

MOT test number 469868233421

MOT #9 2021-09-13 12:16

MOT test number 597242323991

Result

Passed

Advice Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))

Advice Rear Brake pad(s) wearing thin Getting close to wear sensor (1.1.13 (a) (ii))

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Both (5.3.4)

(a) (i))

Result

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8		2020-09-21 11:31
MOT test i	number	700699145144
Result		✓ Passed
Advice	Both front and near side rear tyres wearing on edges	
Advice	Front anti roll bar bushes split	

MOT #7	2019-10-02 10:05
MOT test number	869413882304
Result	✓ Passed
MOT #6	2018-10-20 10:18
MOT test number	778420821070
Result	✓ Passed
MOT #5	2018-10-12 15:33

831086619871
× Failed

MOT #4		2017-10-18 16:21
MOT test	number	266278622681
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Engine plastic plate bottom fitted	
Advice	Engine cover	
Advice	Sill cover under vehicle	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3	2016-10-24 07:47
MOT test number	287410135108
Result	✓ Passed
MOT #2	2015-08-20 17:50
MOT test number	260734946575
Result	✓ Passed
MOT #1	2015-08-19 08:15
MOT test number	328785064083
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Mumber of plates	,
Current registration	NE NE
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-07-28
Last registration	2023-12-22
Complete history	See info



Registration #1	2012-07-28	18 mi
Registration #2	2015-08-19	48.999 mi
Registration #3	2015-08-20	48.999 mi
Registration #4	2016-10-24	65.064 mi
Registration #5	2017-10-18	89.877 mi
Registration #6	2018-10-12	110.066 mi
Registration #7	2018-10-20	110.500 mi
Registration #8	2019-10-02	124.383 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		n

More info >

page 12/13 CarCheck.co.uk



report date: 2024-03-29

Car features

60225	Air conditionin
60295	
60482	
60501	
0566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1998 mm
Height	1796 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2150 kg
Max. allowed weight	2950 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	65196031016305

CarCheck.co.uk page 13/13