



report date: 2024-03-29

General information

Make	FIAT
Model	FIORINO 16V MULTIJET SX
Colour	White
Year of manufacture	2012
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1	
Date	2022-01-23
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-15
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	29
Total items failed	5

MOT #13	2024-04-16 12:10
MOT test number	375369890471
Result	✓ Passed
Next expiry date	2025-04-15
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2024-04-05 12:55

MOT test number

270814619828

Result**✗ Failed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #11

2023-04-11 15:48

MOT test number

520651395080

Result**✓ Passed****MOT #10**

2023-04-11 10:42

MOT test number

602036906468

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9

2022-01-21 14:42

MOT test number

129481735060

Result**✓ Passed**

**MOT #8** 2019-09-20 13:10**MOT test number** 257238662702**Result** ✓ Passed**MOT #7** 2019-09-18 08:20**MOT test number** 988558779239**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-09-26 14:16**MOT test number** 827364074140**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2017-10-02 13:14**MOT test number** 998216916227**Result** ✓ Passed**MOT #4** 2016-11-15 15:40**MOT test number** 381734617813**Result** ✓ Passed

**MOT #3** 2016-11-15 15:40**MOT test number** 381237492696**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2015-10-23 08:42**MOT test number** 485008054503**Result** ✓ Passed**MOT #1** 2015-10-22 16:37**MOT test number** 491521799764**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 April 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YR62VTG
Plate since	2019-09-29
Current registration	YR62VTG
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-21
Last registration	2024-04-16
Complete history	See info



Registration #1	2012-11-21	8 mi
Registration #2	2015-10-22	25.992 mi
Registration #3	2015-10-23	25.992 mi
Registration #4	2016-11-15	37.259 mi
Registration #5	2016-11-15	37.259 mi
Registration #6	2017-10-02	42.172 mi
Registration #7	2018-09-26	56.654 mi
Registration #8	2019-09-18	71.794 mi
Registration #9	2020-05-20	85.377 mi
Registration #10	2021-05-20	95.377 mi
Registration #11	2022-05-20	105.377 mi
Registration #12	2023-05-20	115.377 mi
Registration #13	2024-05-20	125.377 mi
Registration #14	2025-05-20	135.377 mi
Registration #15	2026-05-20	145.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4792743