




report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-09-29
Pictures	5
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-03-16
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	22
Total items failed	4

MOT #11 2024-03-12 11:22**MOT test number** 855543120935**Result** ✓ Passed**Next expiry date** 2025-03-16**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Front Fog lamps missing**Advice** Offside Front Nail in tyre**MOT #10** 2023-03-17 14:47**MOT test number** 174738168160**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2021-09-09 15:27**MOT test number** 623699643673**Result** ✓ Passed**MOT #8** 2020-12-02 16:00**MOT test number** 604135985317**Result** ✓ Passed

**MOT #7**

2019-11-04 14:48

MOT test number

991654085555

Result

✓ Passed

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Mid to rear exhaust joins heavily corroded and 2 rear hangers
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both lower arm rear bushes deteriorated and split (5.3.4 (a) (i))
- Advice** Covers fitted not allowing full inspection
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

MOT #6

2019-10-31 12:34

MOT test number

544791046958

Result

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Mid to rear exhaust joins heavily corroded and 2 rear hangers
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Covers fitted not allowing full inspection
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both lower arm rear bushes deteriorated and split (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

MOT #5

2018-10-26 14:23

MOT test number

886750276762

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2017-11-02 11:33**MOT test number** 722748087535**Result** ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened Offside front brake disc (3.5.1i)

MOT #3 2016-12-21 16:32**MOT test number** 391050438647**Result** ✓ Passed**MOT #2** 2016-12-21 10:26**MOT test number** 832073219658**Result** ✗ Failed

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2015-12-30 09:50**MOT test number** 287063900414**Result** ✓ Passed

Advice No acceleration detected for smoke test



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DN62ZZA
Plate since	2019-03-29
Current registration	DN62ZZA
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-08
Last registration	2024-03-12
Complete history	See info



Registration #1	2013-01-08	29 mi
Registration #2	2015-12-30	28.588 mi
Registration #3	2016-12-21	42.225 mi
Registration #4	2016-12-21	42.225 mi
Registration #5	2017-11-02	49.625 mi
Registration #6	2018-10-26	56.503 mi
Registration #7	2019-10-31	63.718 mi
Registration #8	2019-10-31	63.718 mi
Registration #9	2019-10-31	63.718 mi
Registration #10	2019-10-31	63.718 mi
Registration #11	2019-10-31	63.718 mi
Registration #12	2019-10-31	63.718 mi
Registration #13	2019-10-31	63.718 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ