





report date: 2022-08-09

General information

Make	ALFA ROMEO
Model	75 BASE
Colour	Grey
Year of manufacture	1988
Top speed	130 mph
Gearbox	3 speed automatic

Engine & fuel consumption

Power	158 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	2.492 cc
Cylinders	6
Fuel type	Petrol



CarCheck.co.uk page 1/12



report date: 2022-08-09

Internet history

Entry 1

Date 2021-09-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2022-08-09

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-10-02
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	5
Total items failed	4
MOT #20	2023-10-03 11:25
MOT test number	366564372369
Result	✓ Passed
Next expiry date	2024-10-02

MOT #19	2022-07-28 14:27
MOT test number	498456972303
Result	✓ Passed

MOT #18	2020-09-17 13:35
MOT test number	719875326495
Result	✓ Passed

MOT #17	2019-12-02 09:14
MOT test number	724603167851
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2022-08-09

MOT test number

Result

Fail Offside Front Body has an unsafe modification wing moulding insecure (6.2.1 (d) (i))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #15

MOT test number

Result

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

 MOT #14
 2017-09-29 12:54

 MOT test number
 984185240641

 Result
 ✓ Passed

MOT #13 2016-09-29 11:07

MOT test number 905062267904

Result ✓ Passed

MOT #12 2015-09-29 13:30

MOT test number 130439104159

Result ✓ Passed

MOT #11 2014-09-29 16:04 737132774243

Advice Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

CarCheck.co.uk page 4/12



report date: 2022-08-09

MOT #10		2013-09-26 16:32
MOT test	number	675499263214
Result		✓ Passed
MOT #9		2012-09-28 09:36
MOT test	number	888382272206
Result		✓ Passed
MOT #8		2011-09-29 14:15
MOT test	number	259822871204
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle o	outside zone 'A' (8.3.1d)
Advice	Nearside Front Brake hose slightly deteriorated (3.6.B.4d)	
MOT #7		2010-09-28 14:24
MOTION		200271070277

MOT #7	2010-09-28 14:24
MOT test number	380371970277
Result	✓ Passed
MOT #6	2009-10-01 15:55
MOT test number	663244479250
Result	✓ Passed
MOT #5	2008-09-30 09:59
MOT test number	353204878293
Result	✓ Passed
MOT #4	2007-09-27 12:54

MOT #4	2007-09-27 12:54
MOT test number	570130077291
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2022-08-09

MOT #3	2006-09-28 12:41
MOT test number	741601476246
Result	✓ Passed
MOT #2	2005-09-28 11:03
MOT test number	604971975262
Result	✓ Passed
MOT #1	2005-09-27 12:01
MOT test number	712600075206
Result	× Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Front Front wheel bearing rough when rotated (2.5.A.2)	

CarCheck.co.uk page 6/12



report date: 2022-08-09

Damage history

Check the damage history for this ALFA ROMEO. See if, where and when this ALFA ROMEO had damage and the car repair costs. We also check if this ALFA ROMEO was scrapped. Download the premium report <u>here</u> for the results.


Damage 1

Date
Category
Type

Damage 2

Date Category

Type



Extra ALFA ROMEO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2022-08-09

Vehicle valuation

What is this car worth? See the vehicle value of this ALFA ROMEO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



F586MLY report date: 2022-08-09

Owner history

e when miscory	
For how long did the current and previous owner(s) have this ALFA ROMEO? How many of ROMEO have? Check it in the premium report and see all owner registrations. Download	

THE PERSON NAMED IN COLUMN TO THE PE	

	More info >
Plate changes	
See in this check if this ALFA ROMEO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2022-08-09

Finance check

Check if this ALFA ROMEO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ALFA ROMEO has been settled.

If not, and you buy this ALFA ROMEO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ALFA ROMEO is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



F586MLY report date: 2022-08-09

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1988-10-25
Last registration	2023-10-03
Complete history	See info



Registration #1	1988-10-25	17 mi
Registration #2	2005-09-27	81.293 mi
Registration #3	2005-09-28	81.293 mi
Registration #4	2006-09-28	82.989 mi
Registration #5	2007-09-27	83.905 mi
Registration #6	2008-09-30	84.621 mi
Registration #7	2009-10-01	85.232 mi
Registration #8	2010-09-28	85.942 mi
Registration #9	2011-09-29	86.434 mi
Registration #10	2012-09-28	86.918 mi
Registration #11	2013-09-26	87.349 mi
Registration #12		11.777 es
Registration #13		9.77 66
Registration #14		71.777 es
Registration #15		9.77 66
Registration #16		71.777 es
Registration #17		9.77 66
Registration #18		71.777 es
Registration #19		D.707 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 66

More info >

CarCheck.co.uk page 11/12



F586MLY report date: 2022-08-09

Dimensions & weight

Width	1630 mm
Height	1400 mm
Length	4330 mm

Additional information

Engine number	AR01646026735

CarCheck.co.uk page 12/12