



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	Red
Year of manufacture	2016
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	92 BHP
Max. torque	221 Nm at 2.500 rpm
Fuel type	Electricity



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-20
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-14
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	11
Total items failed	7

MOT #7	2023-05-15 14:55
MOT test number	587127563514
Result	✓ Passed
Next expiry date	2024-05-14
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #6	2023-05-15 08:31
MOT test number	452530328189
Result	✗ Failed
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #5	2022-03-25 14:39
MOT test number	492283440950
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge tyre worn to wear markers (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread rear plate is stained (0.1 (b))

**MOT #4**

2022-03-21 13:10

MOT test number

434452523512

Result**✗ Failed****Fail** Nearside Rear Tyre has ply or cords exposed 195/55/16 (5.2.3 (d) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Rear Registration plate deteriorated but not likely to be misread rear plate is stained (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge tyre worn to wear markers (5.2.3 (e))**MOT #3**

2021-04-01 11:19

MOT test number

365216376591

Result**✓ Passed****Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect misting (5.3.2 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #2**

2019-12-11 11:14

MOT test number

101146169661

Result**✓ Passed****MOT #1**

2019-12-11 09:24

MOT test number

592646323503

Result**✗ Failed****Advice** Offside Rear daytime running light insecure**Fail** Offside Front Headlamp insecure (4.1.1 (c))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 May 2024

Tax status	Valid until 1 January
-------------------	-----------------------

Days left	246
------------------	-----

MOT expiry date	14 May 2024
------------------------	-------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	GD66XPO
Plate since	2024-03-29
Current registration	GD66XPO
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-23
Last registration	2023-05-15
Complete history	See info



Registration #1	2016-12-23	18 mi
Registration #2	2019-12-11	77.653 mi
Registration #3	2019-12-11	77.653 mi
Registration #4	2021-04-01	112.067 mi
Registration #5	2023-05-15	112.067 mi
Registration #6	2023-05-15	112.067 mi
Registration #7	2023-05-15	112.067 mi
Registration #8	2023-05-15	112.067 mi
Registration #9	2023-05-15	112.067 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1480 kg
Max. allowed weight	1966 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5

Engine number C038381