





report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK320 ELEGANCE
Colour	Black
Year of manufacture	2004
Top speed	150 mph
0 - 60 mph	8.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	218 BHP
Max. torque	310 Nm at 3.000 rpm
Engine capacity	3.199 сс
Cylinders	6
Fuel type	Petrol
Consumption city	18.0 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.2 mpg
CO2 emission	254 g/km
CO2 label	L



CarCheck.co.uk page 1/14



Internet history

Entry	, 1
Ellel y	, -

Lifety 1	
Date	2021-06-05
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-03-26
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	32
Total items failed	1

MOT #18	2024-03-27 14:44
MOT test number	870355701361
Result	✓ Passed
Next expiry date	2025-03-26
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #17		2023-03-20 17:25
MOT test	number	437528022186
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or ligh	nt sources (4.7.1 (b)
Advice (e))	Rear Tyre worn close to legal limit/worn on edge Both nearside and offside wo	orn inner edge (5.2.3
Advice	Front Wheel bearing has slight play Both nearside and offside (5.1.3 (a) (i))	

CarCheck.co.uk page 3/14



MOT #16 2023-03-20 09:14

MOT test number 421727799909

Result X Failed

Advice Rear Tyre worn close to legal limit/worn on edge Both nearside and offside worn inner edge (5.2.3 (e))

MAJOR Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Front Wheel bearing has slight play Both nearside and offside (5.1.3 (a) (i))

MOT #15 2022-02-23 17:45

MOT test number 810327636703

Result \sqrt{ Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #14 2021-03-01 12:48

MOT test number 367616367447

Result ✓ Passed

MOT #13 2021-02-20 09:48

MOT test number 339300660907

Result X Failed

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 4/14



LR54CXY

report date: 2024-03-29

MOT #12 2020-03-12 13:23

MOT test number 714440938741

Advice Offside Rear Inner Tyre slightly damaged/cracking or perishing Edge (5.2.3 (d) (ii))

MOT #11 2019-02-16 10:52

MOT test number 430095187768

Result \(\sqrt{Passed} \)

MOT #10 2018-03-13 11:09

MOT test number 769130027737

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear coil spring corroded (2.4.C.1b)

MOT #9 2017-03-10 12:59

MOT test number 822538163891

Result \rightarrow Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2015-12-07 12:21

MOT test number 932857766290

MOT #7 2014-11-15 10:56

MOT test number 206109314334

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14



MOT #6 2013-09-19 09:30

MOT test number 185172163240

MOT #5 2012-08-08 08:32

MOT test number 358181522274

Result

✓ Passed

MOT #4 2011-06-23 10:07

MOT test number 507934771106

Result \(\sqrt{Passed} \)

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Front Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #3 2009-12-08 17:33

MOT test number 870172549317

Advice Rear brake disc slightly pitted (3.5.1h)

Advice Nearside Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)

Advice Front brake disc slightly pitted (3.5.1h)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2008-05-08 15:34

MOT test number 761089328174

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

Advice Rear Service brake: service brake efficiency only just met. It would appear that the braking

system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 6/14



MOT #1 2008-05-08 15:34

MOT test number 290209328119

Result X Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

Advice Rear Service brake: service brake efficiency only just met. It would appear that the braking

system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NE AIS UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-09-22
Last registration	2024-03-27
Complete history	See info



Registration #1	2004-09-22	9 mi
Registration #2	2008-05-08	30.558 mi
Registration #3	2009-12-08	34.481 mi
Registration #4	2011-06-23	34.487 mi
Registration #5	2012-08-08	41.770 mi
Registration #6	2013-09-19	45.388 mi
Registration #7	2014-11-15	47.431 mi
Registration #8	2015-12-07	50.691 mi
Registration #9	2017-03-10	52.309 mi
Registration #10	2018-03-13	54.742 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 13/14



			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1740 mm
Height	1413 mm
Length	4643 mm
Wheel base	2690 mm
Kerb weight	1730 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11295531733787

CarCheck.co.uk page 14/14