





report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI E SPORT
Colour	Red
Year of manufacture	2009
Top speed	120 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2021-11-15
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #11	2020-11-16 12:17
MOT test number	593916739561
Result	✓ Passed
Next expiry date	2021-11-15
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #10	2019-05-14 15:32
MOT test number	423055744734
Result	✓ Passed
Advice Under tray fitted	

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #9 2019-05-06 14:17

MOT test number 489621770211

Result X Failed

Fail Obligatory mirror missing windsreen mirror (3.3 (a))

Advice Front Brake pad(s) wearing thin n/s and o/s (1.1.13 (a) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Under tray fitted

Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

MOT #8 2018-11-27 19:44

MOT test number 210447714211

Advice Under trays fitted

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

CarCheck.co.uk page 3/12



MOT #7 2018-11-27 19:44

MOT test number 160129255102

Result X Failed

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Under trays fitted

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #6 2017-11-24 09:56

MOT test number 252220630158

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2016-11-28 09:34

MOT test number 137481769941

Result
✓ Passed

MOT #4 2015-04-23 15:40

MOT test number 785653415101

Result ✓ Passed

MOT #3 2014-05-07 15:13

MOT test number 718467124123

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2	2013-05-22 14:23
MOT test number	935912143104
Result	✓ Passed
MOT #1	2012-05-09 15:52
MOT test number	119450632173

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax expired: 17 December 2020

X MOT

Expired: 15 November 2021

Tax status Expired at 17 December 2020

Days left 1230 days too late

MOT expiry date 15 November 2021

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		ve?

manage of the same		
	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-07-26
Last registration	2020-11-16
Complete history	See info



Registration #1	2009-07-26	18 mi
Registration #2	2012-05-09	21.453 mi
Registration #3	2013-05-22	31.195 mi
Registration #4	2014-05-07	43.790 mi
Registration #5	2015-04-23	53.189 mi
Registration #6	2016-11-28	57.961 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number BLS B01113