





report date: 2024-03-29

### General information

Make	VOLVO
Model	XC60 D3 SE
Colour	Bronze
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 сс
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2021-07-24
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #9	2020-06-25 06:57
MOT test number	348833787498
Result	✓ Passed
Next expiry date	2021-07-24
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2020-06-25 06:57
MOT test number	825222754470
Result	<b>★</b> Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice Offside Rear Bra	ke pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

MOT #7	2019-07-18 10:02
MOT test number	650354923906
Result	<b>✓</b> Passed

CarCheck.co.uk page 2/10



**Advice** 

**MOT test number** 

Result

**AV60JXW** 

report date: 2024-03-29

418995273734

✓ Passed

MOT #6

MOT test number

Result

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #5
 2017-07-25 07:59

 MOT test number
 580723730892

**Result** ✓ Passed

**MOT #4** 2016-09-21 09:31

Result \( \sqrt{Passed} \)

**MOT #3** 2015-09-21 08:46

**MOT test number** 583605096909

Result \rightarrow Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2014-09-18 11:40

**MOT test number** 248441064298

**Notice** O/S And N/S Rear Tyres Are Perished (235/65/17) 4x4

Notice O/S And N/S Rear Tyres Are Perished (235/65/17) 4x4

Both rear tyres are worn on the inner edge

**Notice** Rear Discs Are Lipped

**MOT #1** 2013-09-25 09:47

**MOT test number** 457018763247

Result \rightarrow Passed

CarCheck.co.uk page 3/10



#### Tax & MOT check



MOT
Expired:
24 July 2021

Tax expired: 28 January 2021

Tax statusExpired at 28 January 2021Days left1188 days too lateMOT expiry date24 July 2021Full MOT historySee MOT history

#### Tax calculation

	·
Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 4/10



AV60JXW

report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

e when miscory	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
***********	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



**AV60JXW** 

report date: 2024-03-29

### Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-09-30
Last registration	2020-06-25
Complete history	See info



Registration #1	2010-09-30	20 mi
Registration #2	2013-09-25	33.885 mi
Registration #3	2014-09-18	44.905 mi
Registration #4	2015-09-21	51.789 mi
Registration #5	2016-09-21	56.838 mi
Registration #6		
Registration #6		
Registration #7		7.77 4
		11.77 m
Registration #7		11.777 mi 11.777 mi 11.777 mi

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditionir
0295	
0482	
0501	
0566	
0567	
0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

# Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pag	e 10/10

Number of axles2Engine number882769