





General information

| Make | KIA |
|---------------------|-----------------------|
| Model | SORENTO CRDI KX-3 ISG |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 124 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 197 BHP |
|-------------------------|---------------------|
| Max. torque | 441 Nm at 1.750 rpm |
| Engine capacity | 2.199 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-06-25 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



MOT history

| MOT expiry date | 2024-07-13 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 3 |

| MOT #7 | 2023-07-06 14:12 |
|--|------------------|
| MOT test number | 503768268599 |
| Result | ✓ Passed |
| Next expiry date 2024-07-1 | |
| Advice Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i)) | |

| MOT #6 | | 2022-07-05 10:40 |
|----------|--|------------------|
| MOT test | number | 447762262282 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #5 | 2021-07-08 14:34 |
|-----------------|------------------|
| MOT test number | 387142550887 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2020-07-14 14:35 |

| MOT test number | 223340771700 |
|-----------------|--------------|
| Result | ✓ Passed |





| MOT #3 | 2020-07-14 12:12 | |
|--|------------------|--|
| MOT test number | 785073344540 | |
| Result | 🗙 Failed | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | | |
| Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | | |
| MOT #2 | 2019-05-14 11:59 | |
| MOT test number | 526650920230 | |
| Result | ✓ Passed | |
| | | |
| MOT #1 | 2018-05-15 10:00 | |
| MOT test number | 294900572806 | |
| Result | ✓ Passed | |
| Advice Nsf tyre has a cut across the tread but not down to cords | | |



Tax & MOT check

| ✓ Taxed Tax due: 1 July 2024 | ✓ MOT Expires: 13 July 2024 |
|---------------------------------------|--------------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 13 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FET I |
| Category | AMP |
| Туре | |
| Damage 2 | AMPLE |
| Damaye z | 6 C C D D |
| Date | 1. St |
| Category | AMP |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| Access of the second seco | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| | |
| Plate since | |
| Plate since Carrent registration | |
| Plata since Carrent registration Plate since | 1000-00-00 |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-05-22 |
| Last registration | 2023-07-06 |
| Complete history | See info |



| Registration #1 | 2015-05-22 | 26 mi |
|-----------------|------------|------------|
| Registration #2 | 2018-05-15 | 16.777 mi |
| Registration #3 | 2019-05-14 | 27.900 mi |
| Registration #4 | 2020-07-14 | 41.353 mi |
| Registration #5 | 2020-07-14 | 41.353 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.177 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 83% |
| Pedestrian | 67% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1890 mm |
| Height | 1685 mm |
| Length | 4780 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1953 kg |
| Max. allowed weight | 2620 kg |
| Additional information | |
| Fuel tank capacity | 71 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/11 |

| Number of axles | |
|-----------------|--|
|-----------------|--|

Engine number

D4HBFH209909