





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TIGUAN SPORT TDI 4MOTION
Colour	Grey
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J



CarCheck.co.uk page 1/13



MC	TC	history	
----	----	---------	--

MOT expiry date	2025-03-27
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	21
Total items failed	12

MOT #16	2024-03-25 15:02
MOT test number	756532389787
Result	✓ Passed
Next expiry date	2025-03-27
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15		2024-03-25 15:02
MOT test number		720629790950
Result		X Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #14		2023-03-28 17:33
MOT test	number	890398871548
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive moveme	ent (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened All. (1.1.14 (a)	(ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 2/13



MOT #13 2022-03-14 12:33

MOT test number 451541736893

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement both sides trailing

arm (5.3.4 (a) (i))

Advice

Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #12 2021-02-19 16:59

MOT test number 949264635233

Result \(\sqrt{Passed} \)

Advice Coolant leak

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

CarCheck.co.uk page 3/13



MOT #11 2020-02-01 12:13

MOT test number 396818018307

Result X Failed

Fail Offside Front Direction indicator not working (4.4.1 (a) (ii))

Advice Front Brake pad(s) wearing thin NS/OS (1.1.13 (a) (ii))

Fail Oil leaking excessively from engine (8.4.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #10 2018-11-15 15:21

MOT test number 637173143856

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9 2018-11-15 11:03

MOT test number 520545966745

Result × Failed

Fail Rear Brake pad(s) less than 1.5 mm thick NS/OS (1.1.13 (a) (ii))

Fail Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/13



Pass with rectification

LTO9HLJ report date: 2024-03-29

MOT #8 2017-08-02 11:27 **MOT test number** 343278633968 Result ✓ Passed 2016-04-11 13:49 MOT #7 **MOT test number** 188907310052 Result ✓ Passed MOT #6 2015-03-04 12:14 **MOT test number** 545403465075 Result ✓ Passed MOT #5 2015-03-04 12:14 975393965064 **MOT test number** Result **X** Failed

MOT #4	2014-03-04 12:37
MOT test number	546273164055
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

Nearside Front Wheel bolt(s) missing (4.2.A.1e)

MOT #3	2013-03-12 16:55
MOT test number	857301173072
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #2

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2012-02-15 16:20
MOT test number	877026742070
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIES
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-09
Last registration	2024-03-25
Complete history	See info



Registration #1	2009-03-09	17 mi
Registration #2	2012-02-15	44.284 mi
Registration #3	2013-03-11	53.126 mi
Registration #4	2013-03-12	53.126 mi
Registration #5	2014-03-04	64.264 mi
Registration #6	2015-03-04	76.193 mi
Registration #7	2016-04-11	83.589 mi
Registration #8	2017-08-02	93.554 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1703 mm
Length	4426 mm
Wheel base	2604 mm
Kerb weight	1604 kg
Max. allowed weight	2260 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 13/13

Engine number

CBA 231905