





report date: 2024-03-28

General information

| Make | TOYOTA |
|---------------------|--------------------|
| Model | URBAN CRUISER D-4D |
| Colour | Purple |
| Year of manufacture | 2010 |
| Top speed | 109 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 205 Nm at 1.800 rpm |
| Engine capacity | 1.364 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 130 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2022-10-09

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-07-31 | |
|---------------|-------------|--|
| Pictures | 1 | |
| Listing price | View report | |



source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-11-07 |
|--------------------|------------|
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 21 |
| Total items failed | 2 |

| MOT #15 | | 2023-11-08 13:14 |
|--|--|------------------|
| MOT test r | number | 557281267371 |
| Result | | ✓ Passed |
| Next expir | y date | 2024-11-07 |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i | i)) |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | | |
| Advice | Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |

| MOT #14 | | 2023-11-08 11:41 |
|----------|--|------------------|
| MOT test | number | 951349124882 |
| Result | | × Failed |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) |) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| MAJOR | Offside Windscreen washer not working (3.5 (a)) | |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |

CarCheck.co.uk page 3/13



(b) (ii))

Result

SY60CPF report date: 2024-03-28

✓ Passed

MOT #13 2022-11-07 12:35

MOT test number 200744410855

Advice Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

Advice Rear Coil spring corroded both sides (5.3.1 (b) (i))

MOT #12 2022-08-05 10:08

MOT test number 384736768057

Result ✓ Passed

MOT #11 2022-08-05 10:08

MOT test number 534450791552

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10 2021-08-12 12:06

MOT test number 891198517607

Advice Rear Coil spring corroded both springs (5.3.1 (b) (i))

MOT #9 2021-02-19 10:27

MOT test number 240153694309

CarCheck.co.uk page 4/13



MOT #8 2020-02-03 17:00

MOT test number 643314679056

Result Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2019-02-27 15:28

MOT test number 262868313971

Result \rightarrow Passed

Advice Offside Rear slight damage to rear door

MOT #6 2018-02-28 12:00

MOT test number 591662987184

Result ✓ Passed

MOT #5 2017-03-01 11:21

MOT test number 479552368852

Result
✓ Passed

Advice Offside Front TYRE WORN ON INSIDE EDGE

MOT #4 2016-02-06 12:23

MOT test number 553264390111

Result
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

| MOT #3 | 2015-01-19 15:41 |
|-----------------|------------------|
| MOT test number | 556959115037 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2014-05-14 12:29 |
| MOT test number | 735634234160 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2013-05-13 16:13 |
| MOT test number | 579243133113 |
| Result | ✓ Passed |

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 1 |
| MOT expiry date | 7 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| • | | |
|--|-----------|-----|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |)TA |
| | | |
| | | |
| | | |
| | | |
| THE STATE OF THE S | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes See in this check if this TOYOTA had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2010-09-07 |
| Last registration | 2023-11-08 |
| Complete history | See info |



| Registration #1 | 2010-09-07 | 12 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-05-13 | 15.579 mi |
| Registration #3 | 2014-05-14 | 49.720 mi |
| Registration #4 | 2015-01-19 | 55.720 mi |
| Registration #5 | 2016-02-06 | 64.814 mi |
| Registration #6 | 2017-03-01 | 72.417 mi |
| Registration #7 | 2018-02-28 | 77.235 mi |
| Registration #8 | 2019-02-27 | 81.939 mi |
| Registration #9 | 2020-02-03 | 87.335 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.117 es |

More info >

CarCheck.co.uk page 12/13



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 58% |
| Children | 71% |
| Pedestrian | 53% |
| Safety systems | 86% |
| Overall rating | 62% |
| Video | see crash video |



Dimensions & weight

| Width | 1725 mm |
|---------------------|---------|
| Height | 1540 mm |
| Length | 3930 mm |
| Wheel base | 2460 mm |
| Kerb weight | 1265 kg |
| Max. allowed weight | 1700 kg |

Additional information

| Fuel tank capacity | 42 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13/1 |

Number of axles 2

Engine number 1ND1128776