





report date: 2024-03-29

General information

Make	MINI
Model	MINI ONE
Colour	Red
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 3

Date 2021-06-07

Pictures 98

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date	2021-02-02	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

Entry 1

Date 2021-01-21	
-----------------	--

Pictures 97

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	7

MOT #14	2023-09-25 13:47
MOT test number	468893742094
Result	✓ Passed
Next expiry date	2024-10-02

MOI#	20	23-09-25 10:45
MOT te	est number	685109035173
Result		X Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii	i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #12	2022-10-03 12:09
MOT test number	958203186224
Result	✓ Passed
Advice Under-trays fitted, obscuring some components	

MOT #11	2022-10-03 10:10
MOT test number	958741224954
Result	× Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Under-trays fitted, obscuring some components	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10	2022-04-06 13:36
MOT test number	289075079405
Result	✓ Passed
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
MOT #9		2021-04-12 15:42
MOT test	number	115451536728
Result		✓ Passed
MOT #8		2020-11-17 12:50
MOT test	number	521184723355
Result		✓ Passed
MOT #7		2019-12-11 14:17
MOT test	number	914332380098
Result		✓ Passed
Advice	Underbody guards fitted obscuring components	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Exhaust has a minor leak of exhaust gases Flexi pipe split and corroded (6.)	1.2 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6 2019-12-11 11:12

MOT test number 636040117411

Result X Failed

Fail Central Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure 175/65/R15 (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working Water in lamp unit (4.2.1 (a) (ii))

Advice Underbody guards fitted obscuring components

Advice Exhaust has a minor leak of exhaust gases Flexi pipe split and corroded (6.1.2 (a))

Fail Offside Front Position lamp not working Water in lamp unit (4.2.1 (a) (ii))

Advice Coolant low

MOT #5 2018-12-05 12:47

MOT test number 142973089429

Result

Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing on shoulder (11 dot code) (5.2.3 (d) (ii))

MOT #4 2017-12-07 11:39

MOT test number 776664058421

Advice Nearside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)

Advice Coolant low

Advice Offside Rear tyre cracked between tread

Advice Oil level low

Advice Rear brake discs worn and corroded slightly

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Nearside Front Road wheel slightly damaged (4.2.A.1a)

MOT #2

MOT test number

463411249466

Result

Advice Nearside Front Tyre worn close to the legal limit wearing on outer edge (4.1.E.1)

MOT #1	2014-12-02 17:19
MOT test number	448836134368
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	

HEREERS	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of sisters	
Current registration	UK NEZ
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 10/13



SB61TVV report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-29
Last registration	2023-09-25
Complete history	See info



Registration #1	2011-12-29	8 mi
Registration #2	2014-12-02	17.968 mi
Registration #3	2015-12-29	21.266 mi
Registration #4	2016-12-20	25.548 mi
Registration #5	2017-12-07	29.932 mi
Registration #6	2018-12-05	33.635 mi
Registration #7	2019-12-11	43.706 mi
Registration #8	2019-12-11	43.706 mi
Registration #9	2020-11-17	50.199 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles2Engine numberB560J085