



HJIIXLH

report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-05-06
Pictures	21
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-06-10
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	18
Total items failed	6

MOT #13 2023-05-18 09:52**MOT test number** 309947573937**Result** ✓ Passed**Next expiry date** 2024-06-10**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MOT #12** 2022-05-16 10:42**MOT test number** 340207362481**Result** ✓ Passed**MOT #11** 2021-05-11 10:53**MOT test number** 295002475802**Result** ✓ Passed**MOT #10** 2020-06-11 09:44**MOT test number** 338776350897**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre



MOT #9	2019-05-14 16:35
MOT test number	206101054687
Result	✓ Passed

MOT #8	2019-05-14 09:59
MOT test number	182070905598
Result	✗ Failed

- Fail** Offside Rear Valve stem seriously damaged (5.2.3 (j))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and worn inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2018-05-14 12:17
MOT test number	111037210134
Result	✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Nail in tyre

**MOT #6**

2018-05-09 13:57

MOT test number

163220106733

Result**✗ Failed****Advice** Nearside Rear Nail in tyre**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5**

2017-05-05 12:59

MOT test number

464622189473

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear tyres perrished in tread**Advice** Offside Rear Nail in tyre**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #4**

2016-05-06 10:52

MOT test number

392707757933

Result**✓ Passed****MOT #3**

2015-05-07 12:16

MOT test number

546117525158

Result**✓ Passed**



MOT #2	2014-10-07 12:46
MOT test number	486140884292
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-10-10 16:53
MOT test number	389903683203
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-03
Last registration	2023-05-18
Complete history	See info



Registration #1	2011-05-03	14 mi
Registration #2	2013-10-10	24.317 mi
Registration #3	2014-10-07	33.503 mi
Registration #4	2015-05-07	36.581 mi
Registration #5	2016-05-06	45.925 mi
Registration #6	2017-05-05	54.035 mi
Registration #7	2018-05-09	59.989 mi
Registration #8	2018-05-14	60.044 mi
Registration #9	2019-05-09	60.044 mi
Registration #10	2019-05-09	60.044 mi
Registration #11	2019-05-09	60.044 mi
Registration #12	2019-05-09	60.044 mi
Registration #13	2019-05-09	60.044 mi
Registration #14	2019-05-09	60.044 mi
Registration #15	2019-05-09	60.044 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	73137786