





report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE 16V
Colour	Grey
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.500 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1


Date 2022-02-07

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2024-11-10
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #15	2023-11-11 10:24
MOT test number	663540921842
Result	✓ Passed
Next expiry date	2024-11-10
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #14	2022-07-16 10:54
MOT test number	988001873958
Result	✓ Passed

MOT #13		2021-06-29 12:09
MOT test	number	688531798104
Result		✓ Passed
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps	s or light sources (4.7.1 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteri	iorated (6.1.7 (g) (i))
Advice	Front Brake disc worn, but not excessively Inner faces (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12 2020-06-30 15:38 **MOT** test number 734960511873 Result ✓ Passed **Advice** Front Tyre slightly damaged/cracking or perishing both front and o/s/r. (5.2.3 (d) (ii)) **Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Advice Nearside Front Anti-lock braking system component slightly damaged (1.6 (e)) Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))Advice Rear Exhaust mounting defective (6.1.2 (a)) **Advice** Rear Passenger seat(s) missing at time of test

MOT #11 2019-07-23 09:57 731335818034 **MOT** test number Result ✓ Passed **MOT #10** 2018-07-17 09:48 **MOT** test number 878285792000 Result ✓ Passed **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9	2017-05-05 09:07
MOT test number	236975206222
Result	✓ Passed
MOT #8	2016-05-18 14:55
MOT test number	726022109465
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7	2015-11-03 17:27
MOT test number	945861729634
Result	✓ Passed
MOT #6	2015-11-03 17:27
MOT test number	174253623973
Result	× Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (8.2.2)
MOT #5	2015-07-21 14:57
MOT test number	547362305218
Result	✓ Passed
MOT #4	2014-08-26 16:24
MOT test number	645398434200
Result	✓ Passed
MOT #3	2013-08-09 14:22
MOT test number	778131623271
Result	✓ Passed
MOT #2	2012-08-16 09:17
MOT test number	528059022263
Result	✓ Passed
NOSuit	V rasseu
MOT #1	2011-08-24 11:48
MOT test number	389666331467

CarCheck.co.uk page 5/12



RX08CXS
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history		
For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAU have? Check it in the premium report and see all owner registrations. Download the full report here .		ULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-04-10
Last registration	2023-11-11
Complete history	See info



Registration #1	2008-04-10	19 mi
Registration #2	2011-08-24	14.122 mi
Registration #3	2012-08-16	15.984 mi
Registration #4	2013-08-09	24.833 mi
Registration #5	2014-08-26	32.101 mi
Registration #6	2015-07-21	42.619 mi
Registration #7	2015-11-03	42.794 mi
Registration #8	2015-11-03	42.794 mi
Registration #9	2016-05-18	43.714 mi
3		
Registration #10		11.777 es
		11.777 ea 11.777 ea
Registration #10		11.77 m
Registration #10 Registration #11		11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12 Registration #13		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1045 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number F054503