





report date: 2024-03-28

General information

| Make | HONDA |
|---------------------|-----------------|
| Model | CIVIC I-DTEC SR |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 125 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 2.000 rpm |
| Engine capacity | 1.597 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 78.5 mpg |
| Consumption extra urban | 83.1 mpg |
| Consumption combined | 80.7 mpg |
| CO2 emission | 93 g/km |
| CO2 label | Α |



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-09-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

| Date | 2021-09-22 |
|------|------------|
| | |

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-09-22 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

CarCheck.co.uk page 2/11



LE18ACU

report date: 2024-03-28

MOT history

| MOT expiry date | 2024-09-09 | |
|--------------------|------------|--|
| MOT pass rate | 75 % | |
| MOT passed | 3 | |
| Failed MOT tests | 1 | |
| Total advice items | 7 | |
| Total items failed | 0 | |

| MOT #4 | 2023-08-23 16:40 |
|------------------|------------------|
| MOT test number | 269622780804 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-09 |

| MO1 #3 | 2023-00-10 13.23 |
|---------------|--|
| MOT test numb | er 211269158634 |
| Result | ★ Failed |
| DANCEROUS | Official Front Tyro trood don'th holow requirements of 1.6mm 235/45/17 (5.2.2 (a)) |

| DANGEROUS | Offside Front Tyre tread depth below requirements of 1.6mm 235/45/17 (5.2.3 (e)) |
|-----------|---|
| DANGEROUS | Offside Rear Tyre tread depth below requirements of 1.6mm 235/45/17 (5.2.3 (e)) |
| DANGEROUS | Nearside Front Tyre tread depth below requirements of 1.6mm 235/45/17 (5.2.3 (e)) |
| DANGEROUS | Nearside Rear Tyre tread depth below requirements of 1.6mm 235/45/17 (5.2.3 (e)) |
| DANGEROUS | Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |

| MOT #2 | | 2022-08-18 07:56 |
|----------|---|------------------|
| MOT test | number | 443005847081 |
| Result | | ✓ Passed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

CarCheck.co.uk page 3/11



MOT #1 2021-09-10 13:49

MOT test number 928547754184

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 156 |
| MOT expiry date | 9 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | | Α |
|---|-----------|---|
| ******** | | |
| | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes See in this check if this HONDA had different number plates. | | |
| Number of plates | | , |
| Current registration | UK NE | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 8/11



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-08-08 |
| Last registration | 2023-08-23 |
| Complete history | See info |



| Registration #1 | 2018-08-08 | 21 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-09-10 | 32.728 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |


More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 75% |
| Pedestrian | 75% |
| Safety systems | 88% |
| Overall rating | 84% |
| Video | see crash video |



Dimensions & weight

| Width | 1779 mm |
|---------------------|---------|
| Height | 1434 mm |
| Length | 4518 mm |
| Wheel base | 2697 mm |
| Kerb weight | 1340 kg |
| Max. allowed weight | 1835 kg |

Additional information

| Fuel tank capacity | 46 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | N16A15203407 |

CarCheck.co.uk page 11/11