



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Black
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-10
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2022-04-05 09:49
<b>MOT test number</b>	371474324616
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-04-04
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge 225-50-17 (5.2.3 (e))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #17</b>	2022-03-25 16:20
<b>MOT test number</b>	868224729884
<b>Result</b>	✗ Failed
<b>Fail</b>	Rear Exhaust has a major leak of exhaust gases Rear back box and rear centre section (6.1.2 (a))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge 225-50-17 (5.2.3 (e))
<b>Minor</b>	Front Windscreen wiper blade defective (3.4 (b) (i))

<b>MOT #16</b>	2021-02-04 12:38
<b>MOT test number</b>	248045690910
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #15</b>	2021-02-04 12:38
<b>MOT test number</b>	261710334605
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Rear Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2020-02-13 14:29**MOT test number** 597382627047**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Centre and rear exhaust corroded**MOT #13** 2019-04-15 14:28**MOT test number** 640220698283**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-04-15 11:39**MOT test number** 592134085311**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2018-04-23 07:34**MOT test number** 811570854021**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2017-04-18 15:45**MOT test number** 664189703369**Result** ✓ Passed**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush in lower trailing arm (2.4.G.2)**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush in lower trailer arm (2.4.G.2)**MOT #9** 2016-04-20 10:10**MOT test number** 975857987283**Result** ✓ Passed**MOT #8** 2015-04-02 11:26**MOT test number** 759662795077**Result** ✓ Passed**MOT #7** 2014-04-07 10:39**MOT test number** 107307794439**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #6** 2013-03-22 09:28**MOT test number** 296281783057**Result** ✓ Passed**Notice** Nail in rear tyre**Notice** Rear silencer corroded**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2012-03-26 09:56**MOT test number** 296556382097**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear seats not fitted at time of test**MOT #4** 2011-03-24 17:00**MOT test number** 835563581019**Result** ✓ Passed**MOT #3** 2011-03-22 12:25**MOT test number** 509361681001**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-12-15 14:20
MOT test number	772119640348
Result	✓ Passed
MOT #1	2010-04-21 11:46
MOT test number	113001010104
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-29
Last registration	2022-04-05
Complete history	<a href="#">See info</a>



Registration #1	2008-04-29	21 mi
Registration #2	2010-04-21	60.321 mi
Registration #3	2010-12-15	80.010 mi
Registration #4	2011-03-22	87.705 mi
Registration #5	2011-03-24	87.705 mi
Registration #6	2012-03-26	97.133 mi
Registration #7	2013-03-22	106.957 mi
Registration #8	2014-04-07	117.178 mi
Registration #9	2015-04-02	127.168 mi
Registration #10	2016-04-20	139.110 mi
Registration #11	2016-04-20	139.110 mi
Registration #12	2016-04-20	139.110 mi
Registration #13	2016-04-20	139.110 mi
Registration #14	2016-04-20	139.110 mi
Registration #15	2016-04-20	139.110 mi
Registration #16	2016-04-20	139.110 mi
Registration #17	2016-04-20	139.110 mi
Registration #18	2016-04-20	139.110 mi
Registration #19	2016-04-20	139.110 mi
Registration #20	2016-04-20	139.110 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1975 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	8D79516