



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T SPIRIT
Colour	Silver
Year of manufacture	2007
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	B



**MOT history**

MOT expiry date	2021-09-15
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	7

MOT #15	2020-09-14 14:21
MOT test number	286364237810
Result	✓ Passed
Next expiry date	2021-09-15
Advice	Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #14	2019-09-16 16:52
MOT test number	745780175394
Result	✓ Passed
Advice	Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #13**

2018-09-14 11:34

MOT test number

325695153238

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #12

2018-09-14 11:34

MOT test number

435750139034

Result

✗ Failed

- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #11

2017-09-14 14:15

MOT test number

519810391627

Result

✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front & both rear (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2016-06-20 07:02**MOT test number** 369983335735**Result** ✓ Passed**MOT #9** 2014-11-03 12:06**MOT test number** 199507804335**Result** ✓ Passed**MOT #8** 2013-11-12 13:04**MOT test number** 459556013318**Result** ✓ Passed**MOT #7** 2013-11-08 11:31**MOT test number** 816462913358**Result** ✗ Failed

Fail Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2012-11-20 15:09**MOT test number** 708195822327**Result** ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #5 2011-11-23 12:23**MOT test number** 239757321357**Result** ✓ Passed

Notice Front brake discs lipped



MOT #4	2011-11-23 12:23
MOT test number	425787521315
Result	✗ Failed
Pass with rectification	Front Headlamp aim too high (1.8)
Notice	Front brake discs lipped
Pass with rectification	Front position lamp(s) not working (1.1.A.3b)

MOT #3	2010-11-27 12:19
MOT test number	291681130306
Result	✓ Passed
Notice	Front brake discs lipped

MOT #2	2010-09-06 12:04
MOT test number	463599540298
Result	✓ Passed

MOT #1	2010-08-17 09:54
MOT test number	371549520495
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YL07HVW
Plate since	2019-03-29
Current registration	YL07HVW
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-07-24
Last registration	2020-09-14
Complete history	See info



Registration #1	2007-07-24	10 mi
Registration #2	2010-08-17	74.204 mi
Registration #3	2010-09-06	74.478 mi
Registration #4	2010-11-27	76.005 mi
Registration #5	2011-11-23	104.002 mi
Registration #6	2012-11-20	132.104 mi
Registration #7	2013-11-08	148.124 mi
Registration #8	2013-11-12	148.456 mi
Registration #9	2019-05-20	25.277 mi
Registration #10	2019-05-20	25.277 mi
Registration #11	2019-05-20	25.277 mi
Registration #12	2019-05-20	25.277 mi
Registration #13	2019-05-20	25.277 mi
Registration #14	2019-05-20	25.277 mi
Registration #15	2019-05-20	25.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NZU155719