





report date: 2024-03-29

#### General information

Make	HYUNDAI
Model	I10 SE
Colour	White
Year of manufacture	2017
Top speed	96 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29


## Internet history

#### Entry 2

Date 2021-02-09

Pictures 8

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-04-20
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	3
Total items failed	5

MOT #8	2024-03-21 13:56
MOT test number	622621649077
Result	✓ Passed
Next expiry date	2025-04-20

MOT #7	2023-04-03 10:30
MOT test number	451641403761
Result	✓ Passed

MOT #6	2023-04-03 07:43
MOT test number	476014181613

Result

Fail

Offside Front Tyre tread depth below requirements of 1.6mm inner and outer edge (5.2.3 (e))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Nail in tyre

Fail Nearside Front Tyre tread depth below requirements of 1.6mm inner and outer edge (5.2.3 (e))

**Advice** Offside Rear Nail in tyre

MOT #5	2022-04-13 11:45
MOT test number	270248201794
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT #4** 2022-04-13 09:42

**MOT test number** 463220785218

**Result** X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3 2021-04-21 10:02

**MOT test number** 701771965098

Result \( \sqrt{Passed} \)

MOT #2 2021-04-21 10:02

MOT test number 937628261154

**Result** X Failed

**Pass with rectification** Offside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt clip broken (2.1.3 (g) (ii))

**MOT #1** 2020-11-17 16:00

MOT test number 862144980848

**Result** 
✓ Passed

**Advice** Front Tyre worn close to legal limit/worn on edge Both tyres worn on both edges, (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	20 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

*	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NE WEE
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



WF67WXD
report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-11-22
Last registration	2024-03-21
Complete history	See info



Registration #1	2017-11-22	18 mi
Registration #2	2020-11-17	14.547 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5	2021-04-21	14.838 mi
Registration #6	2021-04-21	14.838 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		D.777 es

More info >

CarCheck.co.uk page 10/11




WF67WXD
report date: 2024-03-29

Car features

S0225	Air conditionir
S0295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** G3LAHM275871