



report date: 2024-03-28

General information

Make	SUZUKI
Model	GRAND VITARA SZ5 DDIS
Colour	Grey
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





MOT history

MOT expiry date	2024-09-26
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	23
Total items failed	0

MOT #9	2023-09-27 13:04
--------	------------------

MOT test number	587660837743
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-26
------------------	------------

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear light damaged
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2022-05-24 16:39

**MOT test number**

564286087608

**Result**

✓ Passed

- Advice** Central Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7**

2021-06-11 16:51

**MOT test number**

666489450088

**Result**

✓ Passed

**MOT #6** 2018-09-27 15:11**MOT test number** 518607395086**Result** ✓ Passed

**Minor** Offside Rear Rear fog lamp lens defective which has no effect on emitted light lense cracked (4.5.1 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear brake pipes coated in grease

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2017-09-15 09:25**MOT test number** 841730977497**Result** ✓ Passed**MOT #4** 2016-09-14 10:04**MOT test number** 733963777666**Result** ✓ Passed**MOT #3** 2015-10-06 14:20**MOT test number** 170644873288**Result** ✓ Passed**MOT #2** 2014-12-31 11:38**MOT test number** 355895464326**Result** ✓ Passed**MOT #1** 2013-12-23 14:58**MOT test number** 768437653300**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	26 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-12-31
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2010-12-31	28 mi
Registration #2	2013-12-23	24.342 mi
Registration #3	2014-12-31	34.197 mi
Registration #4	2015-10-06	42.578 mi
Registration #5	2016-09-14	49.487 mi
Registration #6	2019-05-29	55.377 mi
Registration #7	2019-05-29	55.377 mi
Registration #8	2019-05-29	55.377 mi
Registration #9	2019-05-29	55.377 mi
Registration #10	2019-05-29	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1880 mm
Height	1695 mm
Length	4575 mm
Wheel base	2640 mm
Kerb weight	1654 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	F9QC-000147