



report date: 2024-03-28

General information

Make	VAUXHALL
Model	CORSA ENERGY
Colour	Black
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	89 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	39.8 mpg
CO2 emission	142 g/km
CO2 label	F








Internet history

Entry 1

Date	2021-10-08
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-14
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #5 2023-11-15 10:37

MOT test number 952508601110

Result ✓ Passed

Next expiry date 2024-11-14

Advice Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement both side's (5.3.4 (a) (i))

Minor Windscreen wiper blade defective (3.4 (b) (i))

MOT #4 2023-11-15 09:00

MOT test number 899695423544

Result ✗ Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement both side's (5.3.4 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2022-10-01 15:16

MOT test number 676932274543

Result ✓ Passed



MOT #2	2022-10-01 08:49
MOT test number	180684201767
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1	2021-09-25 10:35
MOT test number	140782891086
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LR68VZW
Plate since	2019-06-29
Current registration	LR68VZW
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-29
Last registration	2023-11-15
Complete history	See info



Registration #1	2018-09-29	27 mi
Registration #2	2021-09-25	20.684 mi
Registration #3	2022-10-01	30.492 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	77%
Pedestrian	71%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1736 mm
Height	1479 mm
Length	4021 mm
Wheel base	2510 mm
Kerb weight	1102 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	B14XER -19TP8994LDD