




report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Grey
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-03-12
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-04
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	58
Total items failed	12

MOT #18	2023-08-05 11:57
MOT test number	474450502379
Result	✓ Passed
Next expiry date	2024-08-04
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Coil spring corroded both (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17**

2023-07-31 11:05

MOT test number

123743390358

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**Fail** Exhaust emissions exceed level of metered smoke for a non-turbo charged engine (8.2.2.2 (b))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Brake pad(s) missing (1.1.13 (c))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Coil spring corroded both (5.3.1 (b) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Rear Service brake imbalanced across an axle (1.2.1 (b) (i))**MOT #16**

2022-07-05 14:48

MOT test number

683467334071

Result**✓ Passed**

**MOT #15**

2022-05-11 16:27

MOT test number

940104741426

Result

✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Front Windscreen wiper not working (3.4 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))

MOT #14

2022-01-06 10:23

MOT test number

167598002532

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Wearing inner edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Wearing outer edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13

2021-01-04 13:30

MOT test number

219591679047

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #12**

2021-01-04 13:30

MOT test number

115539533407

Result

✗ Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11

2020-01-02 09:49

MOT test number

267618028660

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #10

2019-01-03 12:09

MOT test number

884476057461

Result

✓ Passed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9

2018-01-07 15:40

MOT test number

430498161576

Result

✓ Passed

Advice Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #8

2017-02-28 11:09

MOT test number

104111694164

Result

✓ Passed

Advice

Front brake pad wear low

**MOT #7** 2016-03-01 16:50**MOT test number** 669269882019**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-02-17 11:54**MOT test number** 706068245086**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nearside rear seat, Child seat fitted not allowing full inspection of adult belt!!**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**Notice** Due to Load in boot, rear seat belt and seat condition not tested!!**Notice** Both front tyres inner and outer shoulder getting smooth!!**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2014-03-01 12:29**MOT test number** 107470864483**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)**Notice** Front brake discs; especially off side wearing thin and corroded

**MOT #4** 2013-02-14 10:18**MOT test number** 337255243013**Result** ✓ Passed

- Notice** Front Brake Discs inner sides corroded and slightly scored
- Notice** Under-trays fitted obscuring some underside components
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Near side wiper clearing 40% of drivers view.
- Notice** Front Tyres inner treads worn.
- Notice** Items removed from driver's view prior to test

MOT #3 2013-02-14 10:18**MOT test number** 158365643001**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)
- Notice** Front Tyres inner treads worn.
- Notice** Under-trays fitted obscuring some underside components
- Notice** Near side wiper clearing 40% of drivers view.
- Notice** Front Brake Discs inner sides corroded and slightly scored
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Items removed from driver's view prior to test

MOT #2 2012-03-05 12:11**MOT test number** 709655362072**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-03-05 12:11
MOT test number	307925662017
Result	✗ Failed
Pass with rectification	Offside Rear fog lamp not working (1.3.2b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 August 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-01-06
Last registration	2023-08-05
Complete history	See info



Registration #1	2009-01-06	20 mi
Registration #2	2012-03-05	35.772 mi
Registration #3	2013-02-14	45.606 mi
Registration #4	2014-03-01	57.802 mi
Registration #5	2015-02-17	65.827 mi
Registration #6	2016-03-01	71.250 mi
Registration #7	2017-02-28	83.983 mi
Registration #8	2018-01-07	92.012 mi
Registration #9	2019-01-03	99.928 mi
Registration #10	2020-01-03	105.351 mi
Registration #11	2021-01-03	110.774 mi
Registration #12	2022-01-03	116.197 mi
Registration #13	2023-01-03	121.620 mi
Registration #14	2024-01-03	127.043 mi
Registration #15	2025-01-03	132.466 mi
Registration #16	2026-01-03	137.889 mi
Registration #17	2027-01-03	143.312 mi
Registration #18	2028-01-03	148.735 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0048476