



General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Black
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	39.2 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1	
Date	2021-12-07
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2025-01-11
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	36
<b>Total items failed</b>	20

**MOT #18** 2024-01-12 09:26**MOT test number** 349559103034**Result** ✓ Passed**Next expiry date** 2025-01-11**Advice** Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #17** 2024-01-04 11:43**MOT test number** 399577937265**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #16** 2022-12-16 15:38**MOT test number** 923587548243**Result** ✓ Passed



MOT #15	2021-12-18 20:13
MOT test number	456388361352
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
Advice	Front Brake hose has slight corrosion to ferrule both side (1.1.12 (f) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14**

2021-10-26 11:00

**MOT test number**

855456775444

**Result****✗ Failed****Fail** Prop shaft joint so worn it is likely to fail front prop rear joint (6.1.7 (c) (ii))**Advice** Exhaust mounting defective various mountings (6.1.2 (a))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front discs (1.1.14 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material various front brake pipes not coated by plastic (1.1.11 (c))**Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Exhaust has a major leak of exhaust gases rear silencer (6.1.2 (a))**Fail** Prop shaft joint so worn it is likely to fail rear prop front joint (6.1.7 (c) (ii))**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Spare tyre defective**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear discs (1.1.14 (a) (ii))**Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #13** 2020-10-06 11:17**MOT test number** 624708865918**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front screen washer not working but nearside washer provides sufficient fluid to clear screen**MOT #12** 2020-10-06 11:17**MOT test number** 629131850423**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front screen washer not working but nearside washer provides sufficient fluid to clear screen**MOT #11** 2019-10-25 11:43**MOT test number** 479395113532**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-09-27 14:31

**MOT test number**

881273485262

**Result**

✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #9**

2018-08-30 15:03

**MOT test number**

145020263494

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #8**

2017-08-24 07:23

**MOT test number**

521682899242

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Rear both tyres worn on inner edge

**MOT #7** 2016-09-20 13:13**MOT test number** 909292211667**Result** ✓ Passed**MOT #6** 2016-08-31 10:11**MOT test number** 344639446816**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a slightly worn bush lower bush (2.7.4)**MOT #5** 2016-08-30 13:51**MOT test number** 660832000124**Result** ✗ Failed**Fail** Nearside Headlamp incorrect colour (1.7.5b)**Advice** Nearside Front Shock absorber has a slightly worn bush lower bush (2.7.4)**MOT #4** 2015-09-09 08:51**MOT test number** 348316313578**Result** ✓ Passed**MOT #3** 2014-08-28 12:17**MOT test number** 375780944423**Result** ✓ Passed**MOT #2** 2014-06-24 13:12**MOT test number** 305925274119**Result** ✓ Passed**Notice** Rear wiper blade split





MOT #1	2014-06-24 13:12
MOT test number	225345774159
Result	✗ Failed
Notice	Rear wiper blade split
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
11 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	11 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-07-06
Last registration	2024-01-12
Complete history	<a href="#">See info</a>



Registration #1	2011-07-06	11 mi
Registration #2	2014-06-24	45.581 mi
Registration #3	2014-08-28	45.976 mi
Registration #4	2015-09-09	55.130 mi
Registration #5	2016-08-30	63.655 mi
Registration #6	2016-08-31	63.685 mi
Registration #7	2016-09-20	63.719 mi
Registration #8	2017-08-24	70.536 mi
Registration #9	2018-08-30	85.030 mi
Registration #10	2019-09-27	96.524 mi
Registration #11	2020-05-20	101.277 mi
Registration #12	2020-05-20	101.277 mi
Registration #13	2020-05-20	101.277 mi
Registration #14	2020-05-20	101.277 mi
Registration #15	2020-05-20	101.277 mi
Registration #16	2020-05-20	101.277 mi
Registration #17	2020-05-20	101.277 mi
Registration #18	2020-05-20	101.277 mi
Registration #19	2020-05-20	101.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2090 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7



Number of axles	2
Engine number	711479