





report date: 2024-03-28

## General information

Make	VAUXHALL	
Model	ANTARA EXCLUSIV CDTI S/S	
Colour	White	
Year of manufacture	2013	
Top speed	117 mph	
Gearbox	6 speed Manual	

# Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-08-11

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## MOT history

MOT expiry date	2024-08-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #11	2023-08-15 08:05
MOT test number	375854853408
Result	✓ Passed
Next expiry date	2024-08-19
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Front Play in steering rack inner joint(s)	

MOT #10		2022-07-25 08:32
MOT test	number	422109858584
Result		✓ Passed
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
<b>Minor</b> (4.7.1 (b)	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps (i))	s or light sources
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Service brake grabbing slightly (1.2.1 (c))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-08-20 16:32

**MOT test number** 952404218577

MOT #8 2021-08-18 13:55

**MOT test number** 564977190161

Result X Failed

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #7 2020-08-20 13:30

**MOT test number** 651275786742

MOT #6 2019-10-09 10:29

**MOT test number** 772248287924

**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2018-10-03 09:29

**MOT test number** 706384017969

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4

MOT test number

Result

Pass with rectification

Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

 MOT #3
 2017-10-03 12:31

 MOT test number
 985789928429

 Result
 ✓ Passed

 MOT #2
 2016-09-08 15:12

 MOT test number
 661280010200

 Result
 ✓ Passed

MOT test number

420870301751

Result

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check





Tax expired: 23 February 2024

Tax status	Expired at 23 February 2024
Days left	66 days too late
MOT expiry date	19 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	

Type

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
2000000	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Mumber of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



MA63LPX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-23
Last registration	2023-08-15
Complete history	See info



Registration #1	2013-09-23	19 mi
Registration #2	2016-09-08	24.320 mi
Registration #3	2016-09-08	24.320 mi
Registration #4	2017-10-03	28.524 mi
Registration #5	2018-10-03	36.720 mi
Registration #6	2018-10-03	36.720 mi
Registration #7	2019-10-09	41.739 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



MA63LPX report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ

CarCheck.co.uk page 12/12