





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|----------------|
| Model | COOPER |
| Colour | White |
| Year of manufacture | 2017 |
| Top speed | 130 mph |
| 0 - 60 mph | 7.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 1.250 rpm |
| Engine capacity | 1.499 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 105 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11





report date: 2024-03-29

Internet history

Entry 1

| Date | 2021-05-26 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: autoonline.co.uk

CarCheck.co.uk page 2/11



KW67VWY
report date: 2024-03-29

| MOT | histor | v |
|-----|--------|---|
| | | , |

| MOT expiry date | 2025-01-11 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 8 |
| Total items failed | 0 |

| MOT #4 | 2024-01-12 09:23 |
|--|------------------|
| MOT test number | 317425170785 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-11 |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #3 | 2022-12-28 09:15 |
|-----------------|------------------|
| MOT test number | 280976068451 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2021-12-15 09:34 |
| MOT test number | 229679623938 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2020-12-18 15:18

MOT test number 861153032649

| MOT test | number | .155052049 |
|----------|--|------------|
| Result | | ✓ Passed |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i |)) |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i) |)) |
| | | |

CarCheck.co.uk page 4/11





Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 33 |
| MOT expiry date | 11 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| Owner | history |
|--------|---------|
| OWITEL | HISLULY |

| For how long did the current and previous owner(s) have this MINI? How many owners dicheck it in the premium report and see all owner registrations. Download the full report I | |
|---|-------------|
| | |
| | |
| | |
| *************************************** | |
| ******** | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | NK NE |
| Plate since | |
| Current registration | NK SILV |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-12-29 |
| Last registration | 2024-01-12 |
| Complete history | See info |



| Registration #1 | 2017-12-29 | 22 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-12-18 | 39.815 mi |
| Registration #3 | | D.777 66 |
| Registration #4 | | 71.777 es |
| Registration #5 | | 71,777 mi |
| Registration #6 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 0501 | |
| 0566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1932 mm |
|---------------------|---------|
| Height | 1414 mm |
| Length | 3821 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1160 kg |
| Max. allowed weight | 1565 kg |

Additional information

| Fuel tank capacity | 40 | |
|-----------------------------------|------------------|-------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 4 page | 11/11 |

Engine number

G047H444