





report date: 2024-03-28

General information

Make	FORD
Model	FOCUS TITANIUM X TDCI 140
Colour	Bronze
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/13



R12DSJ report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-30

Pictures 10

Listing price View report









source: autoonline.co.uk

CarCheck.co.uk page 2/13



R12DSJ report date: 2024-03-28

MOT history

MOT expiry date	2025-03-01
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	24
Total items failed	4

MOT #15	2024-02-21 12:04
MOT test number	359607198592
Result	✓ Passed
Next expiry date	2025-03-01
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #14	2024-02-21 12:04
MOT test number	284571425361
Result	★ Failed
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Rear Exhaust mounting defective (6.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2023-03-02 12:09

MOT test number 344113890560

Result ✓ Passed

Advice Rear Exhaust mounting defective 2x rear mountings detached, previous temporary repair to rear. system secure at time of test, recommend attention (6.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12 2023-03-02 12:09

MOT test number 455019972084

Result X Failed

Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Rear Exhaust mounting defective 2x rear mountings detached, previous temporary repair to rear. system secure at time of test, recommend attention (6.1.2 (a))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

MOT #11 2022-03-01 16:12

MOT test number 889235239197

Result

Passed

CarCheck.co.uk page 4/13



MOT #10

R12DSJ report date: 2024-03-28

2020-10-13 17:05

MOT test number 792806194756

MOT #9 2019-04-25 17:05

MOT test number 304856569817

Result ✓ Passed

MOT #8 2018-04-19 08:21

MOT test number 159320028899

Result
✓ Passed

MOT #7 2017-04-11 07:49

MOT test number 555080697397

Result \(\sqrt{Passed} \)

MOT #6 2016-04-13 12:43

MOT test number 884145412555

Result ✓ Passed

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #5 2015-04-13 17:21

MOT test number 248963305431

Notice Vehicle's internal headlight adjuster altered to recheck lights

MOT #4 2014-04-22 14:22

MOT test number 449012414151

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Framework

MOT test number

Framework

MOT #2

MOT test number

577698002109

Result

Notice Engine undershield fitted

Notice Offdie front and nearside front tyres worn on the edges

Notice Cut in offside front tyre sidewall

MOT #1 2012-04-17 13:05 618928402123 **MOT** test number Result × Failed **Notice** Cut in offside front tyre sidewall Pass with rectification Nearside Front Headlamp aim too low and too far to the right. (1.8) Engine undershield fitted Notice Notice Offdie front and nearside front tyres worn on the edges Pass with rectification Offside Front Headlamp aim too low and too far to the right. (1.8)

CarCheck.co.uk page 6/13



R12DSJ report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



R12DSJ report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor science

R12DSJ

More info >

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FORD had different number plates. dear of plates

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



R12DSJ report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-30
Last registration	2024-02-21
Complete history	See info



Registration #1	2009-04-30	9 mi
Registration #2	2012-04-17	14.460 mi
Registration #3	2013-04-23	19.082 mi
Registration #4	2014-04-22	22.181 mi
Registration #5	2015-04-13	25.547 mi
Registration #6	2016-04-13	29.102 mi
Registration #7	2017-04-11	51.990 mi
Registration #8	2018-04-19	35.023 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

9B03425