



PF55EAW

report date: 2024-03-29

General information

Make	SUZUKI
Model	WAGON-R+ GL
Colour	Silver
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg








Internet history

Entry 1

Date	2021-06-11
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #15	2021-07-08 14:26
MOT test number	767435795328
Result	✓ Passed
Next expiry date	2022-07-07

MOT #14	2021-07-07 13:57
MOT test number	525525346885
Result	✗ Failed

Fail Nearside Steering rack has excessive free play detected at the steering wheel (steering rack fitted)
(2.3 (a) (i))

MOT #13	2020-11-02 14:39
MOT test number	761770532859
Result	✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both front discs slightly worn scored (1.1.14 (a) (ii))

Advice Rear Coil spring corroded both rear coil springs corroded (5.3.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Front Coil spring corroded both front coil springs corroded (5.3.1 (b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12**

2019-10-15 13:35

MOT test number

341884461261

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11

2018-10-16 13:50

MOT test number

494077404715

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #10

2017-10-20 12:52

MOT test number

404385633725

Result

✓ Passed

- Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)
- Advice** Both rear tyre sidewalls starting to crack and perish

MOT #9

2016-09-30 13:53

MOT test number

323942498208

Result

✓ Passed



MOT #8	2015-10-26 14:02
---------------	------------------

MOT test number	404592809322
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2014-10-20 10:53
---------------	------------------

MOT test number	768623294221
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	------------------------------------------

MOT #6	2013-10-11 13:53
---------------	------------------

MOT test number	275544683275
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2012-10-05 13:49
---------------	------------------

MOT test number	109969772257
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-10-24 13:58
---------------	------------------

MOT test number	906547891243
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2010-10-27 10:46
---------------	------------------

MOT test number	143280800349
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
---------------	---------------------------------------------------------------------------------------------------------------------------------

MOT #2	2009-12-11 14:41
---------------	------------------

MOT test number	983735149328
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2008-12-12 11:06
MOT test number	423507848445
Result	✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	PF55EAW
Plate since	2019-03-29
Current registration	PF55EAW
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-12-30
Last registration	2021-07-08
Complete history	See info



Registration #1	2005-12-30	11 mi
Registration #2	2008-12-12	8.721 mi
Registration #3	2009-12-11	11.783 mi
Registration #4	2010-10-27	12.889 mi
Registration #5	2011-10-24	13.893 mi
Registration #6	2012-10-05	16.029 mi
Registration #7	2013-10-11	20.094 mi
Registration #8	2014-10-20	24.919 mi
Registration #9	2015-10-26	29.755 mi
Registration #10	2016-10-26	35.577 mi
Registration #11	2017-10-26	41.399 mi
Registration #12	2018-10-26	47.221 mi
Registration #13	2019-10-26	53.043 mi
Registration #14	2020-10-26	58.865 mi
Registration #15	2021-07-08	64.687 mi
Registration #16	2021-07-08	64.687 mi
Registration #17	2021-07-08	64.687 mi

More info >



Dimensions & weight

Width	1620 mm
Height	1695 mm
Length	3540 mm
Wheel base	2360 mm
Kerb weight	1055 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z12XEP19FM279