





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Black
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg



CarCheck.co.uk page 1/9



MOT history

MOT #10 2022-10-22 14:12

MOT test number 875068371173

Result \sqrt{ Passed

Next expiry date 2023-10-21

Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #9 2021-04-15 16:41

MOT test number 864485347588

Result ✓ Passed

MOT #8 2020-06-22 08:45

MOT test number 774168772281

Result ✓ Passed

MOT #7 2019-05-01 16:25

MOT test number 540031229372

Result \(\sqrt{Passed} \)

Advice Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #6 2019-05-01 09:46

MOT test number 239351415397

Result ★ Failed

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-04-19 15:17

MOT test number 591820706279

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 2/9



MOT #4 2018-04-19 11:15

MOT test number 909242535485

Result X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2017-05-02 15:46

MOT test number 368042817577

Result ✓ Passed

MOT #2 2017-05-02 09:28

MOT test number 828235397324

Result X Failed

Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2016-04-29 09:06

MOT test number 984118808641

Result
✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 3/9



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 5/9



Owner history

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in		TC

	More info >	
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		9
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 6/9



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 7/9



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-05-17
Last registration	2022-10-22
Complete history	See info



Registration #1	2013-05-17	19 mi
Registration #2	2016-04-29	20.137 mi
Registration #3	2017-05-02	36.758 mi
Registration #4	2017-05-02	36.758 mi
Registration #5	2018-04-19	56.641 mi
Registration #6	2018-04-19	56.642 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		10.377 esc

More info >

CarCheck.co.uk page 8/9



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 pag	ge 9/9