



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Silver
Year of manufacture	2007
Top speed	142 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-09-11
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-05-26
Pictures	0
Listing price	View report

source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	31
Total items failed	19

MOT #17	2023-07-13 08:52
MOT test number	403769248050
Result	✓ Passed
Next expiry date	2024-07-24

MOT #16	2022-07-25 13:56
MOT test number	454170681132
Result	✓ Passed

MOT #15	2022-05-07 15:24
MOT test number	548094581165
Result	✗ Failed

- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14	2021-06-07 12:29
MOT test number	954666349871
Result	✓ Passed

- Advice** Central exhaust leak



MOT #13	2020-12-14 16:07
MOT test number	236398214220
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Advice	OSR PARKING BRAKE READING LOW
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Fail	Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))

MOT #12	2019-11-01 17:01
MOT test number	820281777714
Result	✓ Passed

**MOT #11**

2019-10-31 09:20

MOT test number

398721302834

Result**✗ Failed**

Advice Offside Front Brake pipe corroded, covered in grease or other material close to excessive (1.1.11 (c))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Lower Suspension arm ball joint likely to become detached foremost (5.3.4 (a) (ii))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material close to excessive (1.1.11 (c))

Advice Nearside Front tyre worn on outer edge

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Central Exhaust has a minor leak of exhaust gases box (6.1.2 (a))

Fail Nearside Front Lower Suspension arm ball joint likely to become detached rearmost (5.3.4 (a) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))

**MOT #10**

2018-06-07 16:15

MOT test number

641034961460

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2018-06-05 10:46

MOT test number

291584084971

Result

✗ Failed

- Fail** Offside Brake pipe excessively corroded front to rear at rear (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #8** 2017-06-03 09:23**MOT test number** 934675945875**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre exhaust box has slight leak
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front exhaust bracket corroded but not broken

MOT #7 2015-12-10 10:18**MOT test number** 858425786027**Result** ✓ Passed

- Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)
- Advice** Offside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)
- Advice** Oil leak

MOT #6 2014-05-16 17:03**MOT test number** 105616334133**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-05-16 14:39**MOT test number** 989316134145**Result** ✗ Failed**Fail** Nearside rear brake binding (3.7.B.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside rear brake binding (3.7.B.1)**MOT #4** 2013-02-23 16:18**MOT test number** 138284253406**Result** ✓ Passed**MOT #3** 2012-03-26 11:55**MOT test number** 426256282089**Result** ✓ Passed**MOT #2** 2011-03-15 13:47**MOT test number** 257114371003**Result** ✓ Passed**MOT #1** 2010-03-12 12:10**MOT test number** 430231470039**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-16
Last registration	2023-07-13
Complete history	See info



Registration #1	2007-03-16	21 mi
Registration #2	2010-03-12	31.252 mi
Registration #3	2011-03-15	40.788 mi
Registration #4	2012-03-26	46.600 mi
Registration #5	2013-02-23	45.994 mi
Registration #6	2014-05-16	64.556 mi
Registration #7	2014-05-16	64.556 mi
Registration #8	2015-12-10	75.212 mi
Registration #9	2017-06-03	88.700 mi
Registration #10	2018-06-05	96.690 mi
Registration #11	2019-06-05	104.680 mi
Registration #12	2020-06-05	112.670 mi
Registration #13	2021-06-05	120.660 mi
Registration #14	2022-06-05	128.650 mi
Registration #15	2023-06-05	136.640 mi
Registration #16	2024-06-05	144.630 mi
Registration #17	2025-06-05	152.620 mi
Registration #18	2026-06-05	160.610 mi
Registration #19	2027-06-05	168.600 mi
Registration #20	2028-06-05	176.590 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1615 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030820577