





General information

Make	VOLKSWAGEN
Model	TRANSPORTER 888 P/V SWB 88BHP TDI
Colour	Blue
Year of manufacture	2003
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	195 Nm at 1.900 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel





Internet history

Entry	1
Date	

Pictures

2021-10-06

12

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-29
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	48
Total items failed	17

MOT #24		2023-08-23 14:56
MOT test	number	658868185298
Result		✓ Passed
Next expiry date 2024-08-2		2024-08-29
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously we	eakened (1.1.14 (a) (ii))





MOT #2	3	2023-08-23 09:46
MOT tes	st number	766124145121
Result		× Failed
Advice	• Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	L4 (a) (ii))
Fail (b) (ii))	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ing	ress of dirt (5.3.4
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	
Fail	Offside Headlamp aim too low (4.1.2 (a))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	L.14 (a) (ii))
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))	
Fail	Horn not working (7.7 (a))	
Fail	Nearside Headlamp aim too low (4.1.2 (a))	
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #22	2022-08-30 09:54
MOT test number	779752620735
Result	✓ Passed
MOT #21	2021-07-20 15:54

MOT test number	549675397168
Result	✓ Passed



LB03UDZ	
report date: 2024-03-29	

МОТ #20	2021-07-20 13:10
MOT test number	851742256389
Result	× Failed
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #19	2020-07-20 16:24
MOT test number	693591977055
Result	✓ Passed

MOT #18	2019-07-15 08:15
MOT test number	446293213208
Result	✓ Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #17	2018-07-19 13:13
MOT test number	501967178949
Result	✓ Passed

MOT #16	2018-07-19 07:46
MOT test number	334424696234
Result	× Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Offside Track rod end ball joint dust cover excessively damaged or deteriorated prevents the ingress of dirt (2.1.3 (g) (ii))	so that it no longer
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but pre dirt (2.1.3 (g) (i))	venting the ingress of
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	





MOT #15		2017-07-21 08:48
MOT test	number	539691716348
Result		✓ Passed
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice (2.2.C.1c)	Offside Track rod end ball joint dust cover deteriorated, but preventing the i	ngress of dirt
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice (2.2.C.1c)	Nearside Track rod end ball joint dust cover deteriorated, but preventing the	e ingress of dirt
MOT #14		2017-07-20 07:58

MOT #14		2017-07-20 07:58
MOT test numb	er	929961483737
Result		🗙 Failed
Advice Offsi (2.2.C.1c)	de Track rod end ball joint dust cover deteriorated, but preventing	the ingress of dirt
Advice Front	t registration plate deteriorated but not likely to be misread (6.3.1	d)
Advice Near (2.2.C.1c)	side Track rod end ball joint dust cover deteriorated, but preventir	ng the ingress of dirt
Fail Fuel sys	tem component leaking ENGINE AREA (7.2.3)	
Advice Rear	registration plate deteriorated but not likely to be misread (6.3.1c	(b

MOT #13		2016-07-13 11:09
MOT test	number	241721084173
Result		✓ Passed
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	



MOT #12	2016-07-12 08:52
MOT test number	800933944389
Result	🗙 Failed
Fail Front brake application uneven (3.7.B.2)	
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its struc	ture (4.1.D.1b)
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #11	20	15-07-27 10:23
MOT test	number	446518805281
Result		✓ Passed
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	

MOT #10		2014-08-04 16:37
MOT test	number	525196114288
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.	1a)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	





MOT #9		2013-07-22 17:24
MOT test	number	176693403214
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1	a)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Under-trays fitted obscuring some underside components	

MOT #8		2012-07-30 10:36
MOT test	number	777252312224
Result		✓ Passed
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Rear Bench seat has some freeplay in locking mechanism - considered secure.	
Notice	N/S/F lower shock absorber bush slightly perished.	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	O/S/F lower shock absorber bush slightly perished.	

MOT #7		2011-08-05 09:29
MOT test	number	835857211268
Result		✓ Passed
Notice	Front number plate discolouring	
Notice	Exhaust system rusty	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	



LB03UDZ
report date: 2024-03-29

MOT #6	2011-08-04 13:40
MOT test number	477156711214
Result	🗙 Failed
Notice Exhaust system rusty	
Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice Front number plate discolouring	
Fail Nearside Rear coil spring incomplete (2.4.C.1a)	

MOT #5	2010-07-23 10:13
MOT test number	393174100437
Result	✓ Passed

МОТ #4	2009-07-22 12:59
MOT test number	483293309287
Result	✓ Passed

MOT #3		2008-07-14 09:20
MOT test	number	212666898116
Result		✓ Passed
Advice	Rear brake disc slightly pitted (3.5.1h)	
Advice Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)		
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Front number plate has slight seperation	

MOT #2	2007-07-18 08:30
MOT test number	893979897193
Result	✓ Passed






MOT #1	2006-07-10 09:49
MOT test number	533641996134
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-08-08
Last registration	2023-08-23
Complete history	<u>See info</u>



Registration #1	2003-08-08	13 mi
Registration #2	2006-07-10	26.233 mi
Registration #3	2007-07-18	32.444 mi
Registration #4	2008-07-14	37.665 mi
Registration #5	2009-07-22	41.705 mi
Registration #6	2010-07-23	45.967 mi
Registration #7	2011-08-04	49.153 mi
Registration #8	2011-08-05	49.153 mi
Registration #9	2012-07-30	51.987 mi
Registration #10	2013-07-22	56.432 mi
Registration #11	2014-08-04	60.297 mi
Registration #12	2015-07-27	64.398 mi
Registration #13	2016-07-12	68.308 mi
Registration #14		11.777 mi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 esi
Registration #23		11.777 esi
Registration #24		11.777 est
Registration #25		11.777 est
Registration #26		11.777 est
		16/17

CarCheck.co.uk

More info >





Car features


S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2175 mm
Height	1940 mm
Length	4707 mm
Kerb weight	1635 kg
Additional information	
Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	4

AJT 161375