





report date: 2024-03-29

#### General information

Make	TOYOTA
Model	IQ VVT-I FIRE AC
Colour	White
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



## Internet history

### Entry 2

Date 2021-07-06

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1


Date	2021-07-06
Pictures	6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #11		2023-10-02 11:23
MOT test	number	640363479354
Result		✓ Passed
Next expi	ry date	2024-10-10
Advice	Nearside Front Tyre slightly damaged/cracking or perishing perished/cra	acked (5.2.3 (d) (ii))
Advice	Nearside front lower suspension arm swivel joint castellated nut locking	device missing .(split pin)
Advice	Offside Front Tyre slightly damaged/cracking or perishing perished/crack	ked (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cor	rds (5.2.3 (d) (i))

MOT #10	2022-10-11 10:32
MOT test number	288629472587
Result	<b>✓</b> Passed

MOT #9	2021-11-16 11:18
MOT test number	823593063445
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



EJ62PCV

report date: 2024-03-29

MOT #8 2021-11-15 10:26

**MOT test number** 761406182818

Result X Failed

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Coolant leak

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2020-12-30 16:28

**MOT test number** 415438937606

Result \square Passed

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #6 2019-12-18 12:54

**MOT test number** 776436290156

**Result** ✓ Passed

MOT #5 2019-12-18 12:54

**MOT test number** 568605918789

**Result** X Failed

**Pass with rectification**Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #4** 2019-01-08 15:50

**MOT test number** 807816958639

**Result** ✓ Passed

CarCheck.co.uk page 4/12



MOT #3	2017-12-01 10:39
MOT test number	856094293543
Result	<b>✓</b> Passed
MOT #2	2016-12-02 09:44
MOT test number	835593465330
Result	<b>✓</b> Passed
MOT #1	2015-12-16 16:25
MOT test number	274148821427
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	10 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
**************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-11-30
Last registration	2023-10-02
Complete history	See info



Registration #1	2012-11-30	7 mi
Registration #2	2015-12-16	42.587 mi
Registration #3	2016-12-02	49.457 mi
Registration #4	2017-12-01	57.029 mi
Registration #5	2019-01-08	64.624 mi
Registration #6	2019-12-18	66.519 mi
Registration #7	2019-12-18	66.519 mi
Registration #8		11.777 ea
Registration #9		0.074
Registration #10		11.777 44
Registration #11		0.074
Registration #12		11.777 ea
Registration #13		11.277 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1615 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	830 kg
Max. allowed weight	1190 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12