




report date: 2024-03-29

General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE DUALOGIC
Colour	Blue
Year of manufacture	2012
Top speed	96 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-05-01
Pictures	1
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-05-03
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	18
Total items failed	7

MOT #18	2024-04-04 07:58
MOT test number	613396657466
Result	✓ Passed
Next expiry date	2025-05-03
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2023-04-24 10:06
MOT test number	569128362969
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2023-04-19 12:04
MOT test number	178289530865
Result	✗ Failed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2022-05-04 16:34**MOT test number** 339135055567**Result** ✓ Passed**MOT #14** 2021-08-10 09:53**MOT test number** 880794470676**Result** ✓ Passed**MOT #13** 2020-09-04 13:35**MOT test number** 423061213204**Result** ✓ Passed**MOT #12** 2020-09-04 12:55**MOT test number** 223074010652**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #11** 2019-09-10 09:46**MOT test number** 363867373808**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge Both fronts (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2019-09-10 09:46**MOT test number** 694109384112**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge Both fronts (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Rear Seat belt not functioning as intended (7.1.2 (c))

**MOT #9** 2018-09-06 08:19**MOT test number** 299660525631**Result** ✓ Passed**Advice** Both rear shock absorber top bushes deteriorated**MOT #8** 2017-09-15 08:06**MOT test number** 595928640073**Result** ✓ Passed**MOT #7** 2017-07-01 10:47**MOT test number** 385567369921**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #6** 2017-07-01 08:51**MOT test number** 511962441421**Result** ✗ Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Front Tyre worn close to the legal limit nail in tyre not repairable (4.1.E.1)**Advice** Nearside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-07-06 10:18**MOT test number** 458815519873**Result** ✓ Passed



MOT #4	2016-04-06 05:45
---------------	------------------

MOT test number	500153350657
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2016-04-06 05:45
---------------	------------------

MOT test number	303593664942
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)
--------------------------------	--

MOT #2	2015-09-21 13:38
---------------	------------------

MOT test number	427546304485
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2015-09-21 13:38
---------------	------------------

MOT test number	588906124900
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Headlamp aim too low (1.8)
--------------------------------	-------------------------------------

Pass with rectification	Offside Headlamp aim too low (1.8)
--------------------------------	------------------------------------



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
3 May 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	3 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-09-27
Last registration	2024-04-04
Complete history	See info



Registration #1	2012-09-27	10 mi
Registration #2	2015-09-21	24.255 mi
Registration #3	2015-09-21	24.255 mi
Registration #4	2016-04-06	26.027 mi
Registration #5	2016-04-06	26.027 mi
Registration #6	2016-07-06	30.404 mi
Registration #7	2017-07-01	37.126 mi
Registration #8	2017-07-01	37.126 mi
Registration #9	2017-09-15	37.274 mi
Registration #10	2018-09-06	43.964 mi
Registration #11	2019-09-06	50.654 mi
Registration #12	2020-09-06	57.344 mi
Registration #13	2021-09-06	64.034 mi
Registration #14	2022-09-06	70.724 mi
Registration #15	2023-09-06	77.414 mi
Registration #16	2024-09-06	84.104 mi
Registration #17	2025-09-06	90.794 mi
Registration #18	2026-09-06	97.484 mi
Registration #19	2027-09-06	104.174 mi
Registration #20	2028-09-06	110.864 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4639928