



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-05
Pictures	47
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	5

MOT #13	2023-12-20 13:34
MOT test number	107595102402
Result	✓ Passed
Next expiry date	2024-12-20
Advice	Rear suspension bushes perishing
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front + Rear suspension components have surface corrosion

MOT #12	2022-12-21 12:02
MOT test number	294171504117
Result	✓ Passed
Advice	Offside Front Macpherson strut ball joint has slight play (5.3.4 (a) (i))
Advice	All rear suspension components have surface corrosion
Advice	Offside Front Play in steering rack inner joint(s)

**MOT #11**

2021-12-03 10:33

MOT test number

890094409681

Result

✓ Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2020-12-21 09:19

MOT test number

970660958677

Result

✓ Passed

Minor Offside Front Windscreen damaged but not adversely affecting driver's view chip in 'a' zone (3.2 (a) (i))**MOT #9**

2020-12-15 12:20

MOT test number

590542537873

Result

✗ Failed

Minor Offside Front Windscreen damaged but not adversely affecting driver's view chip in 'a' zone (3.2 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge wear on inner edge of tread (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear shock absorber ram sheath adrift of mounting point**Fail** Offside Rear Shock absorbers insecurely attached top mount broken (5.3.2 (a) (i))**MOT #8**

2019-12-10 10:29

MOT test number

114709041203

Result

✓ Passed

**MOT #7** 2018-12-06 11:14**MOT test number** 285270933324**Result** ✓ Passed**MOT #6** 2018-12-05 11:45**MOT test number** 734843153028**Result** ✗ Failed

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge bald on inside (5.2.3 (e))

MOT #5 2017-11-29 09:16**MOT test number** 872429956518**Result** ✓ Passed**MOT #4** 2016-12-19 13:08**MOT test number** 288786466593**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)

Advice Nearside Front tyre worn on edges

MOT #3 2016-12-16 09:56**MOT test number** 709080003902**Result** ✗ Failed

Advice Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

Fail Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)

Advice Nearside Front tyre worn on edges



MOT #2	2015-11-27 09:21
MOT test number	129016843284
Result	✓ Passed

MOT #1	2014-12-02 09:26
MOT test number	998766634349
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SD61WUV
Plate since	2019-09-28
Current registration	SD61WUV
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-06
Last registration	2023-12-20
Complete history	See info



Registration #1	2011-12-06	12 mi
Registration #2	2014-12-02	31.140 mi
Registration #3	2015-11-27	39.721 mi
Registration #4	2016-12-16	51.707 mi
Registration #5	2016-12-19	51.753 mi
Registration #6	2017-11-29	61.659 mi
Registration #7	2018-12-05	72.639 mi
Registration #8	2018-12-06	72.643 mi
Registration #9	2019-12-20	75.277 mi
Registration #10	2020-12-20	75.277 mi
Registration #11	2021-12-20	75.277 mi
Registration #12	2022-12-20	75.277 mi
Registration #13	2023-12-20	75.277 mi
Registration #14	2024-03-28	75.277 mi
Registration #15	2024-03-28	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212