



General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-07-08
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-07
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-29
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	56
Total items failed	13

MOT #16	2023-08-30 15:14
---------	------------------

MOT test number	886134367488
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-29
------------------	------------

- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor

Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Both sides. (1.1.14 (a) (ii))
- Advice

Exhaust system corroded.
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2023-08-30 09:48

MOT test number

188155576112

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides. (1.1.14 (a) (ii))**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust system corroded.**Fail** Rear Exhaust emissions likely to be affected by an exhaust leak Box. (8.2.2.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14**

2022-08-06 11:08

MOT test number

346888551730

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Tyre worn close to legal limit/worn on edge Both worn and out of shape inner edges (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Tyre worn close to legal limit/worn on edge On legal limit (5.2.3 (e))**MOT #13**

2021-06-29 13:35

MOT test number

913953173063

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #12

2020-06-04 11:39

MOT test number

151648821413

Result

✓ Passed

- Advice

Central Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2020-06-03 11:41

MOT test number

295875981275

Result

✗ Failed

- Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Valve stem seriously damaged (5.2.3 (j))
- Fail** Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Valve stem seriously damaged (5.2.3 (j))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut too cords on inner side wall (5.2.3 (d) (i))

MOT #10

2019-05-03 16:35

MOT test number

723208636975

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine cover and under-tray fitted
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-04-13 16:35**MOT test number** 591985608232**Result** ✓ Passed**MOT #8** 2018-04-13 10:37**MOT test number** 691953509614**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2017-03-15 17:05**MOT test number** 755214876162**Result** ✓ Passed**MOT #6** 2017-03-15 09:49**MOT test number** 290738845185**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened Face (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit Worn on inner edge (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-02-24 15:19**MOT test number** 596620002183**Result** ✓ Passed**Advice** Engine covers and belly pans fitted**Advice** Both front tyres wearing on edges

**MOT #4**

2016-02-24 15:19

MOT test number

965924738452

Result

✗ Failed

Advice Both front tyres wearing on edges**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Engine covers and belly pans fitted**MOT #3**

2015-02-25 10:53

MOT test number

978676955062

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** DAMAGE TO OUTER WALL OF N/S/R TYRE**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2**

2014-03-20 14:45

MOT test number

295079674003

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** BOTH REAR TYRES WEARING ON EDGES**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #12013-04-16 13:07

MOT test number609646003114

Result

✓ Passed

- Notice

Under-trays fitted obscuring some underside components
- Notice

DAMAGE TO OUTER WALLS OF BOTH N/S FRONT AND REAR TYRES
- Notice

Engine covers fitted obscuring some components in the engine bay
- Notice

BOTH N/S FRONT AND REAR TYRES WEARING ON EDGES



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
29 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-30
Last registration	2023-08-30
Complete history	See info



Registration #1	2010-04-30	18 mi
Registration #2	2013-04-16	33.883 mi
Registration #3	2014-03-20	42.426 mi
Registration #4	2015-02-25	50.615 mi
Registration #5	2016-02-24	57.061 mi
Registration #6	2016-02-24	57.061 mi
Registration #7	2017-03-15	63.555 mi
Registration #8	2017-03-15	63.555 mi
Registration #9	2018-04-13	72.132 mi
Registration #10	2018-04-13	72.132 mi
Registration #11	2019-04-13	72.132 mi
Registration #12	2019-04-13	72.132 mi
Registration #13	2019-04-13	72.132 mi
Registration #14	2019-04-13	72.132 mi
Registration #15	2019-04-13	72.132 mi
Registration #16	2019-04-13	72.132 mi
Registration #17	2019-04-13	72.132 mi
Registration #18	2019-04-13	72.132 mi
Registration #19	2019-04-13	72.132 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080