



report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Grey
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #12</b>	2018-05-03 13:03
<b>MOT test number</b>	230879734241
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2019-05-02
<b>Advice</b>	Front Vehicle structure has slight corrosion radiator cross member (6.1.A.1)
<b>Advice</b>	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
<b>Advice</b>	Rear rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)
<b>Advice</b>	Offside Front coil spring corroded (2.4.C.1b)
<b>Advice</b>	Nearside Front Oil leak driveshaft oil seal
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Shock absorber has a light misting of oil (2.7.3)
<b>Advice</b>	Nearside Front coil spring corroded (2.4.C.1b)
<b>Advice</b>	Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

<b>MOT #11</b>	2017-04-19 13:25
<b>MOT test number</b>	638883519647
<b>Result</b>	✓ Passed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #10 2017-04-12 16:22

MOT test number 857550026606

Result ✗ Failed

- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Horn not working (1.6.2a)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Emissions not tested (7.3.A.1)

MOT #9 2016-04-04 13:27

MOT test number 371439657421

Result ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2016-03-30 14:54**MOT test number** 691084635969**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2015-04-02 17:15**MOT test number** 319552395053**Result** ✓ Passed**Notice** Advise both front brake discs worn**MOT #6** 2015-04-02 13:52**MOT test number** 137582895400**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Advise both front brake discs worn**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2014-03-07 16:10**MOT test number** 146166664013**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-02-26 11:28**MOT test number** 875917954094**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Offside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)

**MOT #3** 2012-10-15 16:28**MOT test number** 269339682299**Result** ✓ Passed**MOT #2** 2012-06-29 15:37**MOT test number** 456721582103**Result** ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Corrosion rear box

**MOT #1** 2011-06-22 10:39**MOT test number** 987043071140**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-06-30
Last registration	2018-05-03
Complete history	<a href="#">See info</a>



Registration #1	2008-06-30	28 mi
Registration #2	2011-06-22	38.259 mi
Registration #3	2012-06-29	48.295 mi
Registration #4	2012-10-15	48.346 mi
Registration #5	2014-02-26	56.695 mi
Registration #6	2014-03-07	56.695 mi
Registration #7	2015-04-02	62.759 mi
Registration #8	2015-05-20	65.277 mi
Registration #9	2015-05-20	65.277 mi
Registration #10	2015-05-20	65.277 mi
Registration #11	2015-05-20	65.277 mi
Registration #12	2015-05-20	65.277 mi
Registration #13	2015-05-20	65.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1267536