



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Silver
Year of manufacture	2008
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-15
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	29
Total items failed	4

MOT #19	2023-08-02 12:02
MOT test number	687707924213
Result	✓ Passed
Next expiry date	2024-08-01
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-08-01 12:13
MOT test number	565744476879
Result	✗ Failed
MAJOR	Nearside Side repeater not working (4.4.1 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2022-06-07 10:50**MOT test number** 519456248237**Result** ✓ Passed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16 2021-06-08 09:12**MOT test number** 596830281271**Result** ✓ Passed**MOT #15** 2020-09-07 15:24**MOT test number** 673759864043**Result** ✓ Passed**MOT #14** 2020-09-04 15:35**MOT test number** 581982277348**Result** ✗ Failed

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #13 2019-09-06 14:42**MOT test number** 223426313334**Result** ✓ Passed

**MOT #12** 2019-09-05 11:51**MOT test number** 190195689345**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #11** 2018-08-28 09:53**MOT test number** 273271003603**Result** ✓ Passed**MOT #10** 2018-08-28 09:53**MOT test number** 162094482174**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #9** 2017-08-30 14:00**MOT test number** 912114572169**Result** ✓ Passed**MOT #8** 2016-09-01 14:20**MOT test number** 308716138092**Result** ✓ Passed

**MOT #7** 2016-03-22 16:57**MOT test number** 762769305063**Result** ✓ Passed**Advice** Child seat fitted not allowing full inspection of seatbelt**MOT #6** 2015-03-30 12:35**MOT test number** 519449285025**Result** ✓ Passed**MOT #5** 2014-03-24 16:35**MOT test number** 167443084498**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2014-03-19 12:22**MOT test number** 896688174089**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-04-03 16:03**MOT test number** 908833193051**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2012-02-21 10:08
MOT test number	689482352052
Result	✓ Passed

MOT #1	2011-02-21 10:55
MOT test number	589642751096
Result	✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Nail in nearside rear tyre
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-26
Last registration	2023-08-02
Complete history	See info



Registration #1	2008-03-26	19 mi
Registration #2	2011-02-21	31.670 mi
Registration #3	2012-02-21	37.157 mi
Registration #4	2013-04-03	40.714 mi
Registration #5	2014-03-19	44.132 mi
Registration #6	2014-03-24	44.132 mi
Registration #7	2015-03-30	47.347 mi
Registration #8	2016-03-22	50.538 mi
Registration #9	2016-09-01	50.675 mi
Registration #10	2017-08-30	66.236 mi
Registration #11	2018-08-28	82.345 mi
Registration #12	2019-08-28	98.454 mi
Registration #13	2020-08-28	114.563 mi
Registration #14	2021-08-28	130.672 mi
Registration #15	2022-08-28	146.781 mi
Registration #16	2023-08-02	162.890 mi
Registration #17	2023-08-02	162.890 mi
Registration #18	2023-08-02	162.890 mi
Registration #19	2023-08-02	162.890 mi
Registration #20	2023-08-02	162.890 mi
Registration #21	2023-08-02	162.890 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

BBM173167