



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM VVT
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 100 km/h	12.0 seconds
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	162 kW / 221 HP / 109 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-23
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	37
Total items failed	6

MOT #14	2023-08-30 12:19
MOT test number	475429239210
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2023-08-30 12:19
MOT test number	195471453025
Result	✗ Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Pass with rectification	Nearside Front Direction indicator with a multiple light source more than 1/2 not functioning blub change. (4.4.1 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))



<b>MOT #12</b>	2022-08-02 08:28
<b>MOT test number</b>	585724985546
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2021-09-01 13:15
<b>MOT test number</b>	433048467939
<b>Result</b>	✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))

<b>MOT #10</b>	2020-08-26 13:44
<b>MOT test number</b>	388449410133
<b>Result</b>	✓ Passed

- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords DEEP CUT IN OUTER SIDE WALL (5.2.3 (d) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated SECURING CLIP LOOSE (6.1.7 (g) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2020-08-26 11:13**MOT test number** 905811539034**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords DEEP CUT IN OUTER SIDE WALL (5.2.3 (d) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated SECURING CLIP LOOSE (6.1.7 (g) (i))**MOT #8** 2019-04-25 09:25**MOT test number** 491051454605**Result** ✓ Passed**Advice** Offside outer cv gaiter poorly secured**MOT #7** 2019-04-24 09:05**MOT test number** 344180160036**Result** ✗ Failed**Fail** Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside outer cv gaiter poorly secured**MOT #6** 2018-04-18 15:04**MOT test number** 579553545800**Result** ✓ Passed



MOT #5	2018-04-18 10:12
MOT test number	887886022652
Result	✗ Failed
Fail	Nearside Front wheel bearing has excessive play (2.5.A.3c)
Fail	Offside Rear Stop lamp not working (1.2.1b)

MOT #4	2017-04-12 08:23
MOT test number	571058517627
Result	✓ Passed
Advice	Under tray fitted
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3	2016-03-30 09:19
MOT test number	779607717849
Result	✓ Passed
Advice	Nearside front side repeater damaged

MOT #2	2015-04-22 10:13
MOT test number	866462815141
Result	✓ Passed
Notice	Nail in offside rear tyre
Advice	Nearside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
Notice	Child seat fitted not allowing full inspection of adult belt



MOT #1	2014-04-15 11:21
MOT test number	748455004137
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Rear seven seat seat belts not fully checked due to seats missing



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>NU11EDR</b>
Plate since	2019-09-28
Current registration	<b>NU11EDR</b>
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-26
Last registration	2023-08-30
Complete history	<a href="#">See info</a>



Registration #1	2011-04-26	26 mi
Registration #2	2014-04-15	24.147 mi
Registration #3	2015-04-22	32.626 mi
Registration #4	2016-03-30	41.897 mi
Registration #5	2017-04-12	50.965 mi
Registration #6	2018-04-18	56.741 mi
Registration #7	2018-04-18	56.742 mi
Registration #8	2019-04-24	64.351 mi
Registration #9	2019-04-24	64.351 mi
Registration #10	2019-04-24	64.351 mi
Registration #11	2019-04-24	64.351 mi
Registration #12	2019-04-24	64.351 mi
Registration #13	2019-04-24	64.351 mi
Registration #14	2019-04-24	64.351 mi
Registration #15	2019-04-24	64.351 mi
Registration #16	2019-04-24	64.351 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1478 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1444 kg
Max. allowed weight	2074 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D089245