



report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-02-08
Pictures	48
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-28
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	25
Total items failed	18

MOT #20	2024-01-29 14:34
MOT test number	806515263363
Result	✓ Passed
Next expiry date	2025-01-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2024-01-29 11:03
MOT test number	857549781154
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm 215 55 16 (5.2.3 (e))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #18** 2023-01-26 10:25**MOT test number** 720105532434**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2022-01-28 15:02**MOT test number** 613268389721**Result** ✓ Passed**MOT #16** 2020-12-11 15:47**MOT test number** 356554542465**Result** ✓ Passed**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**MOT #15** 2020-12-11 15:47**MOT test number** 528442867967**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #14** 2019-12-13 12:58**MOT test number** 973960167266**Result** ✓ Passed

**MOT #13** 2019-12-11 18:51**MOT test number** 316455623579**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Windscreen washer not working (3.5 (a))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #12** 2018-12-06 18:53**MOT test number** 426236804692**Result** ✓ Passed**MOT #11** 2018-12-06 18:53**MOT test number** 143576859710**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Windscreen washer not working (3.5 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**MOT #10** 2017-12-05 17:53**MOT test number** 101012035137**Result** ✓ Passed

**MOT #9** 2017-12-05 17:53**MOT test number** 222931126480**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2016-12-01 10:14**MOT test number** 867836424994**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2016-11-30 17:57**MOT test number** 670994740921**Result** ✗ Failed**Fail** Fuel hose leaking (7.2.3)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Brake pedal anti-slip provision loose (3.3.A.1b)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2015-12-18 11:59**MOT test number** 236753253028**Result** ✓ Passed

**MOT #5** 2015-12-17 19:15**MOT test number** 787387170431**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Near side rear tyre wall slight damage**Fail** Nearside Windscreen wiper blade insecure (8.2.2)**MOT #4** 2014-12-11 19:28**MOT test number** 226365744319**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Off side front spot light damaged**MOT #3** 2014-12-11 19:28**MOT test number** 446355944459**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Rear Electrical wiring inadequately supported (1.9.2a)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Off side front spot light damaged**MOT #2** 2013-07-15 08:53**MOT test number** 598926493139**Result** ✓ Passed



MOT #1	2013-03-22 14:29
MOT test number	707151583027
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
28 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	28 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-05-19
Last registration	2024-01-29
Complete history	<a href="#">See info</a>



Registration #1	2010-05-19	28 mi
Registration #2	2013-03-22	18.524 mi
Registration #3	2013-07-15	20.074 mi
Registration #4	2014-12-11	26.296 mi
Registration #5	2015-12-17	30.571 mi
Registration #6	2015-12-18	30.571 mi
Registration #7	2016-11-30	32.816 mi
Registration #8	2016-12-01	32.816 mi
Registration #9	2017-12-05	37.163 mi
Registration #10	2017-12-05	37.163 mi
Registration #11	2018-12-06	41.199 mi
Registration #12	2019-05-29	45.235 mi
Registration #13	2019-05-29	45.235 mi
Registration #14	2019-05-29	45.235 mi
Registration #15	2019-05-29	45.235 mi
Registration #16	2019-05-29	45.235 mi
Registration #17	2019-05-29	45.235 mi
Registration #18	2019-05-29	45.235 mi
Registration #19	2019-05-29	45.235 mi
Registration #20	2019-05-29	45.235 mi
Registration #21	2019-05-29	45.235 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0059558