





report date: 2024-03-28

## General information

Make	KIA
Model	CEED 1
Colour	Silver
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	124 BHP
Max. torque	154 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.8 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/13



LB11VPK

report date: 2024-03-28

# Internet history

## Entry 1

Date 2021-02-01

Pictures 3

Listing price <u>View report</u>







source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-21
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	8
Total items failed	10

MOT #15	2023-06-07 09:09
MOT test number	621149462669
Result	<b>✓</b> Passed
Next expiry date	2024-06-21

MOT #14		2023-06-07 09:09
MOT test number		822797437791
Result		🗙 Failed
Pass with rectification	Direction indicator incorrect colour BOTH rear (4.4.3 (a))	
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Pass with rectification	Side repeater incorrect colour BOTH sides (4.4.3 (a))	

MOT #13	2022-06-22 15:33
MOT test number	157741722808
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



LB11VPK

report date: 2024-03-28

MOT #12 2022-06-15 15:43

**MOT test number** 726697606902

Result X Failed

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #11** 2021-06-22 07:10

**MOT test number** 539804595240

**Result** ✓ Passed

**MOT #10** 2021-06-22 07:10

**MOT test number** 758221726998

**Result** X Failed

**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))

MOT #9 2021-03-31 07:28

**MOT test number** 598280114679

**Result** X Failed

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #8 2020-03-13 16:21

**MOT test number** 468950156622

Advice O/s/f,n/s/r and o/s/r tyres perished

CarCheck.co.uk page 4/13



LB11VPK

report date: 2024-03-28

MOT test number

Result

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice All tyres perished

MOT test number

Result

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Advice Nearside Tyre slightly damaged/cracking or perishing both tyres starting to perish on sidewalls (5.2.3 (d) (ii))

 MOT #5
 2018-03-16 14:39

 MOT test number
 523365662910

 Result
 ✓ Passed

 MOT #4
 2017-03-31 11:18

 MOT test number
 687600703603

 Result
 ✓ Passed

 Advice
 N/s/wiper poor condition

MOT #3

MOT test number

Result

Advice Wipers slightly poor condition

2016-04-01 12:08

951327384271

✓ Passed

CarCheck.co.uk page 5/13



MOT #2 2015-03-19 11:35

**MOT test number** 855908375088

**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #1** 2014-08-01 13:47

**MOT test number** 625553114288

**Notice** Child seat on rear seat not fitted at time of test

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	21 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



$\alpha$	ner	hict	001
UVV	пег	msi	$\mathbf{o} \mathbf{v}$
		11100	<b>U</b> 1

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
THE STATE OF THE S	
***************************************	
***************************************	
THE PARTY OF THE P	
***************************************	
***************************************	
	More info >
Plate changes	
Flate Changes	
See in this check if this KIA had different number plates.	
Number of plates	9
Francis and Anthropia	NIE.
Cornect registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-07-22
Last registration	2023-06-07
Complete history	See info



Registration #1	2011-07-22	18 mi
Registration #2	2014-08-01	8.863 mi
Registration #3	2015-03-19	12.898 mi
Registration #4	2016-04-01	15.155 mi
Registration #5	2017-03-31	15.858 mi
Registration #6	2018-03-16	18.247 mi
Registration #7	2019-03-29	25.736 mi
Registration #8	2020-03-12	32.155 mi
Registration #9	2020-03-13	32.155 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		9.777 66

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1790 mm
Height	1480 mm
Length	4260 mm
Wheel base	2650 mm
Kerb weight	1291 kg
Max. allowed weight	1730 kg

# Additional information

Fuel tank capacity	53 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 p	age 13/13

Number of axles 2

**Engine number** G4FC9Z128165