




report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO MULTIJET DYNAMIC
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





MOT history

MOT expiry date	2021-11-15
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	29
Total items failed	10

MOT #11	2020-10-28 13:21
MOT test number	577258107529
Result	✓ Passed
Next expiry date	2021-11-15
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust heatshield insecure
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-10-28 12:27
MOT test number	650006231881
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust heatshield insecure
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #9** 2019-05-16 12:56**MOT test number** 407596404915**Result** ✓ Passed**MOT #8** 2019-05-15 09:24**MOT test number** 592316832445**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-04-16 10:24**MOT test number** 739730002865**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #6** 2017-04-21 14:04**MOT test number** 908461140441**Result** ✓ Passed**Advice** Rear coil spring corroded (2.4.C.1b)**MOT #5** 2016-04-26 09:10**MOT test number** 545720005572**Result** ✓ Passed**Advice** No smoke detected no printout**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear tyre sidewall deterioration**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 26% (3.7.B.5b)

**MOT #4**

2016-04-26 09:10

MOT test number

350792297721

Result**✗ Failed****Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 26% (3.7.B.5b)**Advice** Offside Rear tyre sidewall deterioration**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** No smoke detected no printout**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3**

2015-04-21 08:08

MOT test number

356761615107

Result**✓ Passed****Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Advise ref emissions test no acceleration de-tected reading k=0.01 1/m**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)



MOT #2	2015-04-13 12:08
MOT test number	486063905191
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Fail	Offside Front Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
Notice	Under-trays fitted obscuring some underside components
Fail	Nearside Front coil spring broken (2.4.C.1a)
Notice	Advise ref emissions test no acceleration de-tected reading k=0.01 1/m
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #1	2014-01-22 15:44
MOT test number	158212924455
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)



Tax & MOT check

✕
Untaxed

Tax expired:
19 January 2021

✕
MOT

Expired:
15 November 2021

Tax status	Expired at 19 January 2021
Days left	1197 days too late
MOT expiry date	15 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YX11UYO
Plate since	2024-03-29
Current registration	YX11UYO
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-03-27
Last registration	2020-10-28
Complete history	See info



Registration #1	2011-03-27	20 mi
Registration #2	2014-01-22	8.492 mi
Registration #3	2015-04-13	26.362 mi
Registration #4	2015-04-21	26.375 mi
Registration #5	2016-04-26	43.819 mi
Registration #6	2016-04-26	43.819 mi
Registration #7	2016-04-26	43.819 mi
Registration #8	2016-04-26	43.819 mi
Registration #9	2016-04-26	43.819 mi
Registration #10	2016-04-26	43.819 mi
Registration #11	2016-04-26	43.819 mi
Registration #12	2016-04-26	43.819 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1105 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4022351